Office	State of New I	Mexico		Form C-103
District I - (575) 393-6161	Energy, Minerals and N	atural Resources		sed July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II - (575) 748-1283	OIL CONSERVATION DIVISION		30-025-26646	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. F		5. Indicate Type of Lease	_
1000 Rio Brazos Rd., Aztec, NM 87410			STATE 🛛 FE	
<u>District IV</u> – (505) 476-3460	Santa Fe, NM	8/303	6. State Oil & Gas Lease No).
1220 S. St. Francis Dr., Santa Fe, NM 87505				
·	ES AND REPORTS ON WEL	IS	7. Lease Name or Unit Agre	ement Name
(DO NOT USE THIS FORM FOR PROPOSA			7. Lease Pulle of Olik Pigit	Amont Mamo
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Maralo 16 State	/	
PROPOSALS.)	· ··· · · · · · · · · · · · · · · · ·	BS CCD	8. Well Number 4	
	ias Well Other			
2. Name of Operator	ALIG	2 0 2 0 1 8	9. OGRID Number	
RMR Operating, LLC	A00	2 0 20 10	281085	
3. Address of Operator	1 73/ 750 4 4 12 4 12 4 12 4 12 4 12 4 12 4 12 4		10. Pool name or Wildcat	
14282 Gillis Rd, Farmers Bra	nch, 1X 75244 REC	CEIVED	Sioux, Tansill-Yates-Seve	n Rivers /
4. Well Location				
Unit Letter F :	1980 feet from the North	th line and 1	980 feet from the W	est line
Section 16	Township 26-S	Range 36-E		
	11. Elevation (Show whether I			y Lea 🕜
	,	JR, KKD, K1, GR, etc.		
	2943' GL			فننم فسيد عدمينا
12. Check Ap	propriate Box to Indicate	Nature of Notice,	Report or Other Data	
NOTICE OF IN		1 0110		_
NOTICE OF IN			SEQUENT REPORT O	
PERFORM REMEDIAL WORK	INT TO PA	REMEDIAL WOR		G CASING 🔲
TEMPORARILY ABANDON		COMMENCE DR	ILLING OPNS. ☐ P AND A	\boxtimes
PULL OR ALTER CASING	P&A NR RM	CASING/CEMEN	T JOB 🔲	
DOWNHOLE COMMINGLE	P&A R			
CLOSED-LOOP SYSTEM				
OTHER:	ப_	OTHER:		
13. Describe proposed or complet	ed operations. (Clearly state a	Il pertinent details, an	d give pertinent dates, includin	g estimated date
			mpletions: Attach wellbore dia	
proposed completion or recon		•	•	
	•			
			inhility	
	•	a of wellbore only. L	"lability	
	Approved for Pluggingunder bond is retaine	d pending rectoration	on atte	
	Approved for Flugger under bond is retaine completion of the C-1	of Specific of Sub)S.	
	under bond is retaile completion of the C-1 Report of Well Plugg	ing which may be it	oua o	
	Report of Well Plugg	nder forms.	7	
	the OCD web page u	2-30-201	_	
	Report of Well Plugg the OCD web page u Restoration Due By	<u></u>		
	(1000)			
<u> </u>				
Spud Date:	Rig Release	Date:		
Space 2010.				
				
I hereby certify that the information ab	ove is true and complete to the	best of my knowledg	e and belief.	
$\rho = \rho = \rho$	<i>'</i> / / .	o .1 .	al.	-11-4
SIGNATURE CLASS	TITLE_	<u> Yresident</u>	DATE 8 1	7/18
Type or print name Han W 1	Sarksdale E-mail addr	ess: <u>Rlan@redn</u>	nountainresources, PHONE: 50	11-412-409
For State Use Only			tom	
\mathcal{N}_{A}	VIII D		- 1	2 /2 8
APPROVED BY:	Kilshen_TITLE P.	F. J.	DATE 08/2	20/2018
Conditions of Approval (if any):				

MARALO 16 STATE #4 (LEA COUNTY, NEW MEXICO)

06/28/18	RODE EQUIP TO LOC – HELD TAILGATE SAFETY MEETING & JSA ON H2S, MOVING EQUIP & RU. @ 7:00 AM BEGAN TO MI EQUIP. SPOKE W/ MARK W/ OCD YESTERDAY – INFORMED HIM OF MIRU. @ 10:30 AM CHANGED OUT CREWS – HELD TAILGATE SAFETY MEETING & JSA ON RU & PPE. FINISHED MI & SET STEEL MAT. RU. NU BOP & CYCLE TESTED – TESTED GOOD. POOH W/ 99 JTS 2-3/8" TBG. CWI. SDFN.
06/29/18	ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING & JSA ON GOOD HOUSEKEEPING & RIH. WAITED ON DRYER TO PUT ON RIG. OPEN WELL – NO PRESS. RIH W/ TBG & TAGGED PLUG @ 3,125'. CIRC HOLE W/ MLF & PRESS TESTED CSG TO 500# PSI – HELD GOOD. SPOTTED 30 SXS CMT ON TOP OF CIBP @ 3,125'. STOOD BACK 2,050' TBG IN DERRICK & LD BALANCE. RU SLICKLINE, RIH & PERF @ 2,050'. POOH & RD SLICKLINE. RIH W/ TBG & SQZ 75 SXS CMT. POOH & WOC; WILL TAG PLUG TOMORROW AM. CWI. SDFN.
	ARRIVED ON LOC — HELD TAILGATE SAFETY MEETING & JSA ON PERF & SQZ. OPEN WELL — NO PRESS. RIH & TAGGED TOC @ 1,858'. STOOD BACK 722' TBG IN DERRICK & LD BALANCE. RU SLICKLNE, RIH & PERF @ 722'. POOH & RD SLICKLINE. RIH W/ TBG & SQZ 40 SXS CMT. POOH & WOC. RIH & TAGGED TOC @ 589'. POOH & LD TD TBG. RU SLICKLINE, RIH & PERF @ 200'. POOH & REMOVED BOP. INSTALLED WH FLANGE & LOADED HOLE. CIRC HOLE W/ 70 SXS CMT INSIDE & OUTSIDE TO SURF. RD. DUG OUT CELLAR & MOVED TBG OUT OF THE WAY. SDFN.
07/01/18	ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING & JSA. OPEN WELL – NO PRESS. VERIFIED CMT @ SURF. CUT OFF WH & ANCHORS. CAPPED WELL & INSTALLED MARKER, COVERED CELLAR & CLEANED LOC. LOADED TUBULARS ON BAD BOY EXPRESS TRUCK. WELL COMPLETE.