

3610 Elkins Road, Midland, Texas 79705 T. 432.684.0057 F. 432.686.7964 www.phxtech.com

August 20, 2018

HOBBS OCD

AUG 2 9 2018 RECEIVED

Oil Conservation Division State of New Mexico 1625 N. French Drive District 1 - Hobbs Hobbs, New Mexico 88240

Attention: Regulatory Department

Re: XTO Energy

Eugene Coats No. 8 Lea County, New Mexico API #30-025-30821 Job No. 63281

Enclosed please find the Survey Data Certification, and the original Plat and one copy of the Survey Report performed on the above referenced well by Phoenix Technology Services, Inc. (P-5 No. 664171). Other information required by your office is as follows:

Name & Title of Surveyor	Drain Hole Number	Surveyed Depths		Dates Performed		Type of Survey
		From	То	Start	End	
Noe Garza	8	0	3,179	8/13/18/	8/13/18	Gyro

A certified plat on which the bottom hole location is oriented both to the surface location and to the lease lines (or unit lines in case of pooling) is attached to the survey report. If any other information is required, please contact the undersigned at the letterhead address and phone number.

Best Regards,

Brittany Carley

Brittany Carley Operations Administrator