

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-10788
5. Indicate Type of Lease STATE FEE XX
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name E.L. Steeler
8. Well Number 006
9. OGRID Number 025504
10. Pool name or Wildcat Langlie Mattix; 7 RVRS, Q-Grayburg

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-103) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☒ INJECTION

2. Name of Operator  
Yarbrough Oil LP

3. Address of Operator  
P.O. Box 1769 Eunice, NM 88231

4. Well Location

Unit Letter J : 1980 feet from the South line and 1980 feet from the East line  
Section 17 Township 23S Range 37E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENT

PERFORM REMEDIAL WORK ☐ F  
TEMPORARILY ABANDON ☐ C  
PULL OR ALTER CASING ☐ I  
DOWNHOLE COMMINGLE ☐

INT TO PA  
P&A NR  
P&A R

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A XX  
CASING/CEMENT JOB ☐

OTHER:

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 9/10/18

Type or print name John R. Stearns, Jr. E-mail address: bobbystearns1@yahoo.com PHONE: 575-760-2482

For State Use Only

APPROVED BY: [Signature] TITLE P.E.S. DATE 09/10/2018

Conditions of Approval (if any):

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.  
Restoration Due By 02-09-2019

E.L. Steeler #6  
API 30-025-10788

2/6/2018 Move equipment and rig up.

2/7/2018 Dug out cellar. One side of the surface head had cement in the connection. The other side did not. There was also about a foot of cement in the cellar. Installed BOP. Worked the tubing free. Laid down 111 joints IPC tubing and an AD-1 packer. The last joint was plugged. Picked up workstring and set 5 1/2" CIBP at 3472'.

2/8/2018 Circulated MLF and tested casing. Casing was good to 600#. Spotted 25 sx cement on top of CIBP. POOH and perforated casing at 2498'. Well kicked while running the packer. Shut down for lunch and let the well blow. Kill the tubing with 20 bbls and the casing with 30 bbls. Finished running packer and set at 2015'. Squeezed perfs with 50 sx cement with CaCl. (Cement volume was increased from 35 sx to 50 sx by the OCD) ISIP of squeeze was 1200#. Waited 45 minutes. Pressure had fallen to 350#. Pressured up again to 1200# with less than 1 bbl and SION.

~~2/9/2018~~ Released packer and tagged cement at 2206'. Perforated casing at 1180'. Could not pump into the perfs. Spotted cement across the perfs from 1235'. POOH and pressured up on the casing to 500#. WOC and tagged cement at 1073'. Perforated casing at 250'. Could not get circulation up the surface head. Pressured up to 600# and held. RIH with tubing to 302' and circulated cement to surface with 35 sx. Rigged down.

2/12/2018 Cut off wellhead. Cement was to surface inside the 8 5/8" casing. Filled up the 5 1/2" casing to surface with less than 1 sack. Installed marker and cut off the anchors.