

Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
District I – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 882400 <u>District II</u> – (575) 748-1283	OH CONGERNATION DIVIGION		30-025-41343
District II – (575) 748-1283 811 S. First St., Artesia, Nr. (58210 District III – (505) 224-518	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
1000 Rio Brazos Aztec, NM 874000	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE S FEE
District IV – (503) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Salita Pe, INIVI 87505		6. State Oil & Gas Lease No.
87505			
SUNDITATION OF THE SUNDITATION O			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			CENTRAL VACUUM UNIT
PROPOSALS.)  1. Type of Well: Oil Well   Gas Well   Other INJECTOR			8. Well Number #170
2. Name of Operator			9. OGRID Number
CHEVRON USA INC		4323	
3. Address of Operator 1616 W. BENDER BLVD HOBBS, NM 88240		10. Pool name or Wildcat	
1616 W. BENDER BLVD HOBBS, NM 88240  4. Well Location		VACUUM; GRAYBURG SAN ANDRES	
Unit Letter <u>L</u> : 2490 feet from the <u>SOUTH</u> line and <u>500</u> feet from the <u>WEST</u> line			
Section 36 Township 17S Range 34E NMPM County LEA			
Section 36 Township 178 Range 34E NMPM County LEA  11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
4019' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS. P AND A
<del></del>	MULTIPLE COMPL	CASING/CEMEN	T JOB
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM  OTHER:		OTHER:	×
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
THE SUBJECT WELL FAILED ITS MIT PLAN TO PERFORM WORKOVER TO RESTORE MECHANICAL INTEGRITY			
AND RETURN TO INJECTION, WORK AS FOLLOWS TO RETURN TO INJECTION.			
<b>09/11/2018</b> MIRU C& J RIG 1475.			
09/11/2018 BLED DOWN FLOWLINE AND N/D SAME. MADE SEVERAL ATTEMPTS TO RIH WITH S/L BUT			
UNSUCCESSFUL.			
09/13/2018 FLOW BACK WELL TO CLEAN UP TUBING.			
ORIGINAL MIT CHART AND A COPY ATTACHED. CONTINUED ON NEXT PAGE			
<u></u>		****	
Spud Date:	Rig Release	Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
$\Lambda$ , at $\Lambda$			
SIGNATURE UNDA MINUS TITLE PERMITTING SPECIALIST DATE 09/25/2018			
Type or print name <u>CINDY HERRERA-MURILLO</u> E-mail address: <u>Cherreramurillo@chevron.com</u> PHONE: <u>575-263-0431</u>			
For State Use Only  A A A A A A A A A A A A A A A A A A A			
APPROVED BY: DATE 9/25/2018			
Conditions of Approval (if any):			

RBAMS-CHART-V





## **WORKOVER PROCEDURE**

**09/14/2018** RIH W/SL AND SET PLUG IN 1.43' PLUG AND SET IN 1.43 F PROFILE AT 4,318/ POOH W/L AND R/D APOLLO. ATTEMPTED TO TEST PLUG TO 1,000 PSI BUT CAUGTH PRESSURE ON THE 5 ½ CASING.

**09/15/2018** CIRCULATED WELL AND TESTED CASING TO 500 PSI FOR 30 MOINUTES ON CHART RECORDER. TEST SUCCESSFUL.

**09/17/2018** N/D TREE AND N/U BOP. TEST COP, RELEASE FROM ON/OFF TOOL AND POOH L/D 2 3/8' FIBER LINED TUBING..

**09/18/2018** REPAIR GATE VALVE ON CASING, TIH W/ON/OFF TOOL AND 2 3/8' J-55 TK-99 TUBING. CIRCULATE PACKER FLUID. HANG TUBING AND TEST BOTH SIDES.

**09/19/2018** ND BOP, NU TREE AND TEST. RIH W/ S/L AND RETRIEVE 1.43' PLUG. PERFORM MIT TEST. TEST CASING TO 560 FOR 30 MINUTES. TEST SUCCESSFUL, N/U INJECTION LINE RISER. R/D C & J 1475. MOVE OFF LOCATION.