HOBBS OCD Submit 3 Copies To Appropriate District Form C-103 Office June 19, 2008 District I SEP 272018 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II 30-025-32623 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III RECEIVED STATE 🖂 FEE 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A State "A" DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator 9. OGRID Number **Chevron USA INC** 3. Address of Operator 10. Pool name or Wildcat 6301 DEAUVILLE BLVD., MIDLAND, TX 79706 Vacuum Drinkard 4. Well Location Unit Letter H 510 : 2310 feet from the NORTH line and feet from the Township Section 31 17S Range 35E **NMPM** County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3976' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL DOWNHOLE COMMINGLE		REMEDIAL WORK ALTERING CASING CASING/CEMENT JOB	<u>/</u>				
OTHER:		OTHER:					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date							

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/21/18: MIRU pulling unit, N/U BOP. 5/22/18: TIH w/ 2-7/8" tubing, latch onto bridge plug, TOH and I/d same, TIH w/ work string, tag PBTD at 7,196', spot MLF t/ 5,984'. 5/23/18: M&P 25 sx CL "C" cement plug f/ 5,984' t/ 5,737', TOH t/ 4,779', M&P 187 sx CL "C" cement f/ 4,779' t/ 2,923' in two stages, TOH w/ tbg, conduct CBL, TIH w/ tbg t/ tag TOC at 2,920', TOH t/ 2,850', M&P 25 sx CL "C" cement f/2,850' t/2,603'. 5/24/18: Sustained casing pressure noted on the intermediate casing string, R/U wireline, RIH and perforate casing at 1,526', attempt to establish rate, unable to inject, RIH w/ second gun and perforate at 1,376', attempt to establish rate, unable to inject, M/U packer and TIH t/ set at 1,450', attempt to establish rate between perforation, achieved slow leak off of 400 psi in 30 minutes. 5/25/18: Unset packer and TOH, M/U CICR and TIH t/ set at 1,507'. 5/29/18: M&P 50 sx CL "C" cement mixed w/ resin, sting into retainer and squeeze all cement mixed w/ resin below retainer, sting out of retainer, M&P 33 sx CL "C" cement mixed w/ resin f/ 1,507' t/ 1,185'. 5/30/18: Sustained intermediate casing pressure noted, TIH and tag TOC at 1,215', TOH w/ tbg, R/U wireline, RIH and perforate casing at 1,090' and at 900', R/D wireline, M/U and TIH w/ packer and set at 1,055', attempt to establish rate without success, unset packer and TOH t/896', R/U wireline and perforate casing at 1,012', TIH and set packer at 1,055', attempt to establish rate without success. 5/31/18: Set packer at 992', attempt rate through perforations at 1,012' without success, TOH w/ packer, TIH w/ open ended tbg t/ tag TOC at 1,215', M&P 28 sx CL"C" gas block cement f/ 1,215' t/ 940', TOH w/ tbg, shut well in and apply 1,800 psi, WOC, perform bubble test, but failed, M/U and TIH w/ packer t/ tag TOC at 965', TOH w/ packer t/ 766'. 6/1/18: TIH w/ packer t/ 965', spot MLF t/ 900', TOH w/ packer t/766', R/U wireline, RIH and perforate casing at 814', TIH w/ packer and set at 868', attempt to establish rate without success, TOH w/ packer t/ 766', R/U wireline and perforate casing at 842', TIH w/ packer and set at 868', attempt to establish rate without success, packer damaged after unsetting, TOH and L/D. 6/2/18: M/U new packer, TIH t/ 831', set packer, attempt to establish rate without success, unset packer and TOH t/ 965' (TOC), circulate well with fresh water in preparation for Zonite placement, TOH and L/D packer, R/U wireline, RIH and perforate casing w/ high density perforation gun at 470'. N/D BOP, R/D 6/4/18; RDMO pulling unit.

6/10/18: MIRU wireline, M/U and TIH w/ roll shot, tag TOC at 965', perforate casing at 958', RDMO wireline, R/U Zonite crew, beginning placing Zonite (total of ~12.7 cuft), recognized Zonite had bridged off high. RDMO Zonite crew.

7/27/18: MIRU CTU, TIH and tag Zonite at 21'. 7/30/18: M/U 4-3/4" bit w/ motor on end of CT, TIH and tag Zonite at 21', drill out t/ 115', fell through, TIH t/ tag TOC at 965', TOH and break out bit, M/U AW scraper, TIH t/ 965' while pumping, circulate well clean, TOH and break out scraper, RDMO CTU.

8/1/18: MIRU Zonite crew, place 26 cuft of Zonite material, tag top of Zonite at 769', RDMO.

^{**}Allow Zonite to hydrate for 2 months**

MIRU CTU, check production, intermediate, and surface casing, no pressure, perform bubble test, no bubbles, well static, RIH w/CT and tag Zonite at 765', M&P 94 sx CL "C" cement f/ 765' t/ surface. RDMO CTU.

Well P&A'd on 9/24/18

I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
$\mathcal{M}_{\mathcal{I}}$								
SIGNATURE	TITLE	Well Abandonment Engineer	DATE	9/26/18				
		_	-	_				
Type or print name Howie Lucas	E-mail address:	howie.lucas@chevron.com	PHONE: (832) 5	588-4044				
For State Use Only								
APPROVED BY: Marh With	Jun TITLE	P.E.S.	DATE	09/27/18				
Conditions of Approval (if any):				· · · · · · · · · · · · · · · · · · ·				

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.

Restoration Due By 2019