

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 03 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-28970
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. COOP 11

7. Surface Location

UL - Lot K	Section 34	Township 18-S	Range 38-E	Feet from 2500	N/S Line SOUTH	Feet From 1660	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 16 July 18	Injecting
-------------	---------	-----------	--------------------	-----------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0	N/R	N/R	8 psi	1016
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

A) Ops: No prod to Nothing

B) No Rise

C) No Rise

D) oily water 1 gal
Small Prod to Nothing

Denise Colon

575.318.5067

Signature: <u>Mendy Johnson</u>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: <u>mendy_johnson@oxy.com</u>	
Date: <u>SEP 26 2018</u>	
Phone: 806-592-6280	
Witness:	