## HOBBS OCD

State of New Mexico

Energy, Minerals and Natural Resources Department OCT 9 2 2018 Oil Conservation Division Hobbs District Office

## BRADENHEAD TEST REPORT

## RECEIVED

			Operator		IEAD IE	SI KEFUK	L		' API Numbe	2r	
Operator Name OCCIDENTAL PERMIAN, LTD								30-025-07360			
Property Name NORTH HOBBS (G/SA) UNIT								Well No. 321 -			
<sup>7.</sup> Surface Location											
UL - Lot G			Range · 38-E		Feet from 2310	N/S Line Feet F NORTH 231		1	E/W Line EAST	County LEA	
Well Status											
Well Status		-	SHUT-IN	PRODUCING		9/14/1 DATE		8		_	
	OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH										
OBSERVED DATA											
If bradenhead flowed water, check all of the descriptions that apply:        (A)Surf-Interm      (B)Interm(1)-Interm(2)      (C)Interm-Prod      (D)Prod Csng      (E)Tubing										(E)Tubing	
Pressure /			-0-	-0-		-0-		357		675 -	
Flow Characteristics						<u> </u>				675	
Puff				Ô N		<b>Ø</b> / N		Y / N			
Steady Flow			Y/Q			Y/			/ N		
Surges				Y/O		Y /O			/ N	_	
Down to nothing Gas or Oil				Y/60		V/N Y/N		Y / N Y / N			
Water			- v / (N)	Y/(N)		Y / N		Y/N			
		<b>I</b>	<u> </u>	L	<u> </u>	·C		l		1	
If bradenhead flowed water, ch						SULFUR					
CLEAR		FRE	SH	SALI	Y	SULF			BLACK		
Remarks: INJECTINGAT THIS TIMEWTR,GAS,CO2											
		۰Š	Sec	1	1 Min	2<	ser				
5 sec Inin 2 sec Bloudown Out OL											
Blordown Blowdown											
Danny lane 575-318-1959 DL											
					Dann	y lane	5	75-316	1-1959	DL	
					•		<del>_</del>				

Signature: Mendy Johnson	OIL CONSERVATION DIVISION				
Printed name: MENDY JOHNSON	Entered into RBDMS				
Title: ADMINISTRATIVE ASSOCIATE	Re-test				
E-mail Address: mendy_johnson@oxy.com					
Date: SEP 2 6 2018 Phone: 806-592-6280					
Witness:					