# HOBBS OCD

## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

## **BRADENHEAD TEST REPORT**

## RECEIVED

	<sup>7</sup> Surface Location			
	Property Name NORTH HOBBS (G/SA) UNIT	Well No. 539	L	
1	Operator Name OCCIDENTAL PERMIAN, LTD	<sup>3</sup> API Number 30-025-36213		

				24	Line Boomie					_
UL Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County	
1	24	18-S	37-Е		2056	SOUTH	1889	EAST	LEA	[
										•

### Well Status

Well Status	SHUT-IN	PRODUCING	DATE	
	NO	Yes	10/11/18	

#### OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

### **OBSERVED DATA**

If bradenhead flowed water, check all of the descriptions that apply:

······	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	-0-	N/A	N/A	400	452
Flow Characteristics	6	····	•		
Puff	0/ N	Y/N	Y / N	Y / N	
Steady Flow	Ø N	Y/N	Y7 N	Y/ N	-
Surges	Y/O	Y / N	Y/N	Y/N	
Down to nothing	()/ N	Y / N	Y/N	Y / N	
Gas or Oil	Y7	Y/N	Y/N	Y/N	1
Water	Y/N)	Y / N	Y/N	Y / N	

### If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK	
Remarks:	3 Sec Blowdown		INJECTING AT THIS TIME		
	Ţ	Junny lune	575-318-1959	DL	

Signature: Mendy Jehnon	OIL CONSERVATION DIVISION		
Printed name: MENDY JOHNSON	Entered into RBDMS		
Title: ADMINISTRATIVE ASSOCIATE	Re-test		
E-mail Address: mendy_johnson@oxy.com	MD		
Date: OCT 1 6 2018 Phone: 806-592-6280			
Witness:			

OCT 2 2 2018