



HOBBS OCD

NOV 26 2018

RECEIVED

FLARE INSPECTION

COG

LEASE OR FACILITY NAME: Condor ST.

WELL # # 1H API # 30- 025 - 40814

U.L. D SEC 20 T 18S R 35E

FOOTAGE 60 NYS 330 E W

IS A FLARE STACK PRESENT? YES NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

COMMENTS: Prod. gas going to sales.

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS: Tank vapors are going to combustor

INSPECTOR Gary Robinson DATE 11-26-18