HOBBS OCD	· · · · · · ·			
NOV 2 9 2018				
	Form C-103			
District I RECEIPINETGY, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	Revised November 3, 2011 WELL API NO.			
District II 811 S. First St., Artesia, NM 88210 District III 1220 South St. Francis Dr.	30-025-25754 5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM	STATE FEE 6. State Oil & Gas Lease No.			
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Fowler State			
1. Type of Well: ☐Oil Well ⊠ Gas Well ☐ Other 2. Name of Operator	8. Well Number 002 -			
Cimarex Energy Co. of Colorado	162683 10. Pool name or Wildcat			
 Address of Operator 202 S. Cheyenne, Suite 1000, Tulsa, OK 74103 	Langlie-Mattix			
4. Well Location - Unit Letter <u>L</u> : <u>231</u> feet from the <u>FF</u> line and <u>999</u> leet from the <u>F</u>				
 Section <u>16</u> Township <u>24S</u> Range <u>37E</u> NMPM County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other D				
	SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORI TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT				
OTHER: All pits have been remediated in compliance with OCD rules and the terms of the Oper	ady for OCD inspection after P&A array and closure plan.			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in	properly abandoned.			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIC PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	ON HAS BEEN WELDED OR			
The location has been leveled as nearly as possible to original ground contour and has leader of the duration equipment	been cleared of all junk, trash, flow lines and			
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines.				
\mathbf{Z} If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure.				
When all work has been completed, return this form to the appropriate District office to scho	edule an inspection.			
	<u>иемал</u> дате <u>3-16-18</u>			
TYPE OR PRINT NAME Mark Bishop E-MAIL: mbishop@ Cin	Officer A DATE 11-29-18			
APPROVED BY: Keny Juther TITLE Compliance	Officer A DATE 11-29-18			
LAST WELL ON LEASE				

				<u> </u>
⊁	LAST WELL	ONZ	£Α	5