Submit One Copy To Appropriate District			Form C-103 Revised November 3, 2011	
District I 1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-025-26541	
811 S. First St., Artesia, NM 8010			5. Indicate Type of Lease	
1000 Rio Brazos Rd., A26C, NM 87410 District IV			STATE     FEE       6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name GETTY 36 STATE COM	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Numbe	
1. Type of Well:     Oil Well     Gas Well     Other       2. Name of Operator			9. OGRID Number	
MARATHON OIL PERMIAN, LLC 3. Address of Operator			372098 10. Pool name or Wildcat	
5555 SAN FELIPE ST, HOUSTON, TX 77056			E. GRAMA RIDGE MORROW	
4. Well Location Unit Letter J 1980 feet from the S line and 1980 feet from the E line				
Unit Letter J: <u>1980</u> feet from the S line and <u>1980</u> feet from the E line Section <u>36</u> Township <u>21S</u> Range <u>34E</u> NMPM County LEA				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3664' GL				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON PREMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI				ALTERING CASING 🔲 ' P AND A 🛛 🗖
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN			TJOB D JPM	
OTHER:				
<ul> <li>All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.</li> <li>Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> </ul>				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> <u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u>				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
Image: The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)				
<ul> <li>All other environmental concerns have been addressed as per OCD rules.</li> <li>Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-</li> </ul>				
retrieved flow lines and pipelines.				
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE	TITLE_CTI	R - Technician HES		DATE 11/8/2018
TYPE OR PRINT NAME Adrian Covarrubias		acovarrubias@marat	honoil.com	PHONE: 713-296-3368
APPROVED BY: Kerry Forther	TITLE_	mpliance É	Officer 1	4 date 11-29-18

1

i se la compañía de l