Whitaker, Mark A, EMNRD

From: Sent: To: Subject: Attachments: Whitaker, Mark A, EMNRD Wednesday, November 28, 2018 1:25 PM 'caitlin.ohair@wpxenergy.com' TORO 27 No. 2 - C103 to inspect location after P&A IMG_0173.JPG; IMG_0174.JPG

30-025-34711

HOBBS OCD

NOV 2 8 2018

RECEIVED

Caitlin,

I can not release this location as I found it today. Found a piece of tubing east of gas meter. Also note there was a meter base and meter on the south side of the location that need to be removed and gas purchasers line blinded off. Please remove the piece of tubing and contact the gas purchaser to request removal of their equipment. Forward a copy of the correspondence to me and I will attach it to the C103. Also let me know when the tubing has been removed.

Respectfully, Mark Whitaker, PES NMOCD, District 1