abandor SUBM 1. Type of Well Oil Well Gas Well 2. Name of Operator MATADOR PRODUCT 3a. Address 5400 LBJ FREEWAY S DALLAS, TX 75240	Contact: TON COMPANYE-Mail: tlink@ma SUITE 1500 e, Sec., T., R., M., or Survey Descriptio 3FSL 523FWL	INTERIOR AGEMENT DRTS ON WELLOBBS o drill or to re-enter an PD) for such prophyses.2 8 (structions on page ECEN TAMMY R LINK tadorresources.com 3b. Phone No. (include area code) Ph: 575-627-2465	OCD CON Control Contro	6 e or Tribe Name greement, Name and/or No. No. DERAL 201H 1-00-X1 or Exploratory Area W-DELAWARE	
12. CHECK 7	THE APPROPRIATE BOX(ES) TO INDICATE NATURE O	F NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSIO	'n	TYPE OF	TYPE OF ACTION		
 Notice of Intent Subsequent Report Final Abandonment N 	 Acidize Alter Casing Casing Repair Change Plans Convert to Injection leted Operation: Clearly state all pertir 		 Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal 	☐ Well Integrity ☑ Other Production Start-up	
following completion of the testing has been completed. determined that the site is re BLM BOND NO:NMB0 Surety Bond No:RLB00 Production Sundry 6/23/2018 Rig Releas 8/13/2018 Held Pre fra Repaired a leak to re-t minutes. Good Test. 8/18/2018 Pressure te	001079 015172	t pump iron to flowback manifol rform integrity test to 5,350 psi :36 17,402'-17,284' through sta	mpletion in a new interval, a Form 3 ing reclamation, have been complete sbad Field Of <u>OCD Hobbs</u> d to 12,500 psi. for 30 nge 21	3160-4 must be filed once and the operator has	
14. I hereby certify that the for Name (Printed/Typed) TA	Electronic Submission For MATADOR	#443043 verified by the BLM We PRODUCTION COMPANY, sent cessing by PRISCILLA PEREZ o Title PRODU	to the Hobbs		
Signature (El	ectronic Submission)	Date 11/07/2			
		OR FEDERAL OR STATE		<u> </u>	
	e attached. Approval of this notice do gal or equitable title to those rights in t to conduct operations thereon.		ZOTA STEVENS TitlePETROLEUM ENGINEER Date 11/08/2018 Office Hobbs		
	Title 43 U.S.C. Section 1212, make it audulent statements or representations		willfully to make to any department	or agency of the United	
(Instructions on page 2)	A REVISED ** BLM REVISE		I REVISED ** BLM REVIS	 ED **	

۰.,

Additional data for EC transaction #443043 that would not fit on the form

32. Additional remarks, continued

. .

1

-

40/70 Mesh 11,649,000 lbs, Total proppant 12,630,000 lbs. 8/25/2018 FDMO, HES frac spread function test BOP's; good test. 9/1/2018 Flowing well to OTT, trace of gas, no oil. Begin flowing through 3 phase separator water to OTT; Gas to flare; no oil. 9/3/2018 Oil to frac tank. 9/27/2018 Well flowing to facility off flowback. Rig up L&R #7 unloaded 300 jts 2 7/8" tubing and 16 GLV's. Pumped 200 bbls of 10# brine. At 30 bbls pressure went up to 1800 psi, at 70 bbls pressure started to drop. Finished pumping pressure was at 1600 psi. Flow back pickup over shot for no/off tool and run in hole picking up 300 jts of 2 7/8" and 16 GLV's. Weatherford design 361 jts 2 7/8" & 16 GLV's. NU tree test void for 30 minutes. Good test. Clean location, well on production.