Submit 3 Copies To Appropriate District Office	State of N	lew Mexico		Form C-103 October 25, 2005	
<u>District I</u>	Energy, Minerals ar	nd Natural Resources	WELL API NO.	, , , , , , , , , , , , , , , , , , , ,	
1625 N. French Dr., Hobbs, NM 88240 District II	5 N. French Dr.,Hobbs, NM 88240			30-025-06003	
1301 W Grand Ave Artesia NM 88210 UIL CONSERVATION DIVISION			5. Indicate Type of Leas	se	
<u>Disrtict III</u> 1000 Rio Brazos Rd. Aztec, NM 87410	1220 South	St. Francis NM 8750	STATE [FEE 🗹	
<u>District IV</u>	Santa Fe,	NM 875 (5)	6. Spe Oil & Gas Leas	e No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		MINI 875(2)		·	
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACKED A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			T. Anderson		
PROPOSALS.)			8. Well Number		
1. Type of Well: Oil Well 🔽 Gas Well 🔲 Other			3		
2. Name of Operator			9. OGRID Number 873		
Apache Corporation 3. Address of Operator			10. Pool Name		
303 Veterans Airpark Ln., Ste. 3000, Midland, TX, 79705			Monument Blinebry		
4. Well Location		_	/		
Unit Letter K : Section 8	2310 feet from the Township 20\$	S line and Range 37E	1650 feet from the		
111	Township 20S Elevation (Show whether		NMPM	County Lea	
	•	3547' GL			
12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data					
12. Officer Appropriate Box 10 indicate Nature of Notice, Freport, of Other Bata					
NOTICE OF INT	ENTION TO:		SUBSEQUENT RE	PORT OF:	
	UG AND ABANDON	REMEDIAL WORK	ALTERING	=	
	ANGE PLANS	COMMENCE DRILLING OF	PNS. D PANDA	✓	
PULL OR ALTER CASING	ILTIPLE COMPL	CASING/CEMENT JOB		/	
<u>—</u>					
OTHER: All pits have been remediated in complian	on with OCD rules and the ter		ready for OCD inspection	after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.					
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the					
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR					
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR					
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.					
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and					
other production equipment.					
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.					
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed					
from the lease and well location.					
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have					
to be removed.) All other environmental concrens have been addressed as per OCD rules.					
All other environmental concrens have been addressed as per OCD rules. J Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from					
non-retrieved flow lines and pipelines.					
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one					
inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.					
\ll . 4	2				
SIGNATURE XIIIM K	WAS TITLE	Sr. Reclamation F	oreman DATE	11/30/18	
TYPE OR PRINT NAME Guinn	Burks	guinn.burks@apache	ecorp.com PHONE:	432-556-9143	
For State Use Only APPROVED BY:	when TITLE	Compliance a	Officer ADATE	12-14-18	
Conditions of Approval (if any):	TILE TILE	- Congression C	HILL WATE	10 1/ 10	