

## **FLARE INSPECTION**

Centerial Resource	'	<b>&gt;</b> /			
LEASE OR FACILITY NAMI					
WELL# <u>502 H</u>	API #	30- <u>a2</u>	<u> </u>	2	
U.L <u>/{/</u> SEC <u>/9</u> T	2/5 R 3	34E	<del></del>		
FOOTAGE <u>600</u> N	<u> 196</u>	63	E W		
IS A FLARE STACK PRESENT?	YES	NO			
IS FLARE ACTIVE?	YES	NO			
IS GAS TO FLARE METERED?	YES	NO			
AREA AROUND FLARE CLEAR	ED? YES	NO			
COMMENTS: Frod. gas	going =	h 54	ales .		
			<del></del>		
IS VRU PRESENT?	YES	NO			
IS VRU ACTIVE?	YES	NO	^	/	
COMMENTS: Tank Vap	ers tied.	into o	Mare -	looks	/12.
More Han ounces	burning	on E	lare.		
	,				
1	,				
INSPECTOR Say fold	mour		DATE _	12-13-	18