



## FLARE INSPECTION

**COG**  
**LEASE OR FACILITY NAME:** Montera Fed.

**WELL #** 23 H **API #** 30- 025 - 43924

**U.L.** N **SEC** 10 **T** 255 **R** 35E

**FOOTAGE** 190 **NYS** 1650 **E** W

**IS A FLARE STACK PRESENT?** ☒ YES ☐ NO

**IS FLARE ACTIVE?** ☒ YES ☐ NO

**IS GAS TO FLARE METERED?** ☒ YES ☐ NO

**AREA AROUND FLARE CLEARED?** ☒ YES ☐ NO

**COMMENTS:** Prod. gas going to sales.

**IS VRU PRESENT?** YES ☒ NO

**IS VRU ACTIVE?** YES ☐ NO

**COMMENTS:** Tank vapors going to combustor

**INSPECTOR** Gacey Robinson **DATE** 1-7-19