


## OK

Submit One Copy To Appropriate District	State of New Me	exico	Form C-103	
Office District I	Energy, Minerals and Natu	ral Resources	Revised November 3, 2011	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	I DIVISION -	<u>30-025-36302</u>	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. From	nais Dr	5. Indicate Type of Lease STATE X FEE	
District IV	Santa Fe, NM 8	1505 A 2013	6 State Oil & Cas Lease Ma	
1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM ST	Qar "O"		)
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	JAN.	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLU	UG BACK TO A	Rio Blanco 9 State	
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FO	DR SQEH		
1. Type of Well: Oil Well	Gas Well Other	1	8. Well Number 1	
2. Name of Operator			9. OGRID Number	
DEVON ENERGY PRODUCTION CO LP			6137	
3. Address of Operator			10. Pool name or Wildcat	
PO BOX 250, ARTESIA, N	M 88211	l	Bell Lake; Devonian, NE Gas	
4. Well Location				
	et from the <u>NORTH</u> line and <u>212</u>		<u>ST_line</u>	
Section <u>9</u> Township	23S Range 34E NMPM	CountyLEA		
	11. Elevation (Show whether DR, 3405' GL	, RKB, RT, GR, etc.)		
12. Check Appropriate Box to		enort or Other Dat		
			un a a a a a a a a a a a a a a a a a a a	
NOTICE OF IN			EQUENT REPORT OF:	
PERFORM REMEDIAL WORK		REMEDIAL WORK		
		COMMENCE DRILL		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT J	IOB [] ./ Pr	
OTHER:		(i breathailteach	Averan management of the source of the sourc	
All pits have been remediated i	n compliance with OCD rules and th	he terms of the Operat	tor's pit permit and closure plan.	
	illed and leveled. Cathodic protection			
	meter and at least 4' above ground l			
	ASE NAME, WELL NUMBER, A DN, TOWNSHIP, AND RANGE.		RTER/QUARTER LOCATION OR	
	PED ON THE MARKER'S SUR		HAS BEEN WELDED UK	
	s nearly as possible to original grou	nd contour and has be	en cleared of all junk, trash, flow lines and	
other production equipment.				
<ul> <li>Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.</li> <li>If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with</li> </ul>				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.		, <u>F</u>	······································	
	als have been removed. Portable ba	ises have been remove	ed. (Poured onsite concrete bases do not have	
to be removed.)				
All other environmental concer	ins have been addressed as per OCD	D  rules.	All fluids have been removed from non-	
retrieved flow lines and pipelines.	een abandoned in accordance with I	19.13.33.10 NWAC. 7	An huids have been removed from hon-	
	t remaining well on lease: all electri	cal service poles and l	lines have been removed from lease and well	
location, except for utility's distribu	tion infrastructure.	-		
When all work has been completed,	return this form to the appropriate I	District office to sched	lule an inspection.	
SIGNATURE Denise Q. D			DATE = 1/2/2010	
SIGNATURE Denuse U. JA			DATE 1/3/2019	
TYPE OR PRINT NAME Denies		FIELD SUPPORT		
For State Use Only	Menoud E-MAIL: <u>denise.men</u>			
For State Use Only	Menoud E-MAIL: <u>denise.men</u>	noud@dvn.com _ PI	HONE:575-746-5544	
	Menoud E-MAIL: <u>denise.men</u>	noud@dvn.com _ PI		







## Menoud, Denise

v · · •

From:	Menoud, Denise		
Sent:	Thursday, January 3, 2019 2:56 PM		
То:	Whitaker, Mark A, EMNRD		
Cc:	karen.sharp@state.nm.us		
Subject:	Rio Blanco 9 State #1 - P&A Reclamation C-103		
Attachments:	Rio Blanco 9 St 1_PA Reclaim C103 Submitted 1.3.19.pdf		

RE: Rio Blanco 9 State #1 30-025-36302

Please see attached C-103 requesting inspection of reclaimed pad. I will also mail the original. Thank you.

## Denise Menoud

Admin Field Support, Completions - Reclamations - Regulatory Office: 575-746-5544 Email: denise.menoud@dvn.com

## Devon Energy

6488 Seven Rivers Hwy PO Box 250, Artesia, NM 88210 575-748-3371

Devon - Internal

1