Submit One Copy To Appropriate District Office	State of New MexicoFEB 1 2 20	Form C-103
District I E	Ingray Minarals and Natural Pasaurass	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II	RECEIV	WELL API NO. 30-025-32271
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE STATE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		NEW MEXICO O STATE NCT-1
PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well Gas W	/ell Other	34 -
2. Name of Operator Chevron Midcontinent, LP		9. OGRID Number 4323
3. Address of Operator		10. Pool name or Wildcat
6301 Deauville Blvd., Midland, TX 79705	;	VACUUM, YATES
4. Well Location:		
Unit Letter P: 380 feet from the SOUTH line and 330 feet from the EAST line		
Section 36 Township 17-S Range 34-E NMPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indic	eate Nature of Notice, Report or Other I	Data
NOTICE OF INTENT	FION TO:	SSEQUENT REPORT OF:
	G AND ABANDON REMEDIAL WOF	
-	— ·	ILLING OPNS. P AND A
PULL OR ALTER CASING MUL	TIPLE COMPL	IT JOB □
OTHER:	□ ⊠ Location is a	ready for OCD inspection after P&X
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
M. The location has been leveled as nearly	, as possible to original around contour and has	haan alaawad of all jumb trook flour lines and
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's part from lease and well location.	pit permit and closure plan. All flow lines, pro-	duction equipment and junk have been removed
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infi		ia mies mave ocen removed nom reast and wen
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE Katherine Papa	george TITLE Decommissioning	Project ManagerDATE2/10/2019
TYPE OR PRINT NAMEKatherine Papageorge_E-MAIL: _Katherine.Papageorge@chevron.com PHONE:832-854-5291		
TYPE OR PRINT NAMEKatherine Papageorge_E-MAIL: _Katherine.Papageorge@cnevron.com PHONE:832-834-3291 For State Use Only		
APPROVED BY: Kerry Forther title Compliance Office A DATE 2-13-19		
APPROVED BY: 'Xenry 'tov	her TITLE Compliance	Uffice H DATE 2-13-19
·	¥	VV