Submit I Copy Office	To Appropriate District	Sta	ate of New Me	xico		Form	C-103	
District 1 - (575		Energy, Mi	nerals and Natur	ral Resources	WELL API NO.	Revised July	18, 2013	
1625 N. French District 11 – (57	Dr., Hobbs, NM 88240 75) 748-1283	OIL CONCEDUATION DIVIGION			WELL API NO.	30-025-23777		
	, Artesia, NM 88210 05) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indicate Type	of Lease		
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410		Santa Fe, NM 87505		STATE	X FEE			
District JV ~ (5 1220 S. St. Fran	05) 476-3460 ncis Dr., Santa Fe, NM	Sa	11141 1 6, 14141 67	303 <u>as</u> Ou	STATE 6. State Oil & G	as Lease No.	0	
87505		CEC AND DEDOI	TC ON WEI RE	CBB	7 Lance Name	or Unit Agreement	10-71	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A) 2019 DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					7. Lease Name (_	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCHO PROPOSALS.)					NORTH V	AC. ABO UNIT		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other INI					8. Well Number	209		
2. Name of Operator CROSS TIMBERS ENERGY, LLC					9. OGRID Num	ber 298299	/	
3. Address	of Operator		``````	PRINT - 44 A.A.	10. Pool name o	r Wildcat		
400 W. 7TH STREET, FORT WORTH, TX 76102					NORTH '	VAC ABO		
4. Well Location Unit Letter J: 1980 feet from the S line and 1780 feet from the E line								
	tion 22	Towns			NMPM	County LEA		
		11. Elevation (S		RKB, RT, GR, etc.	.)			
4050.2 GR								
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data								
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:								
PERFORM	REMEDIAL WORK 🔯	PLUG AND ABA		REMEDIAL WOR		ALTERING CASI	NG 🖂	
	RILY ABANDON	CHANGE PLAN	s 🗍		RILLING OPNS.	P AND A		
	LTER CASING	MULTIPLE CON	MPL	CASING/CEMEN	IT JOB			
	E COMMINGLE OOP SYSTEM							
OTHER:	DOP STSTEW			OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date								
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of								
proposed completion or recompletion.								
EXPEDITE: Expected RU date: 02/20/2019								
During a remedial cement job on the North Vacuum Abo Unit #209 to place cement in the 5-1/2" x 8-5/8" casing annulus, a casing failure in the 8-5/8" resulted fluid coming to surface outside the 8-5/8" surface casing. Cementing operations were halted with only a few bbls of cement remaining in the tubing. After sting								
out of the cement retainer and circulating the tubing clean, the well was shut-in to allow the cement to cure. There was no flow from the 8-5/8" casing after ceme								
pumping operations stopped. Dirt was removed from around the wellhead and surface casing revealing a split and crimp in the 8-5/8" 6-7 feet below ground lev To remediate the casing failure, the following is proposed:								
	ted RU date: 02/20/2019							
гарес								
1. MIRU pulling unit. PU tubing and casing spear and spear into 5-1/2" casing. Pull in tension. 2. Cut and remove failed section of 8-5/8" casing. Inspect 5-1/2" casing for crimp or damage. Repair 8-5/8".								
3. Hang casing back in new wellhead.								
4.	Resume clean-out oper	ations on well to clean	out cement, remove R	BP, and return well to	injection per approved (C-103 dated 10/29/2018.		
Spud Date:	05/25/1971		Rig Release Da	te: 06/	/21/1971			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
SIGNATURE	Smamll	x baulle	TITLE Regulat	ory Technician	D	ATE 02/15/2019		
Ĺ	→	•				HONE, 917 324 77	17	
Type or print name Samanntha Avarello E-mail address: sangeles@mspartners.com PHONE: 817-334-7747 For State Use Only								
	.,		mun - 1	1 1.011	_	1 10 1	6	
	APPROVED BY: Lacy foliage TITLE Complexies Office DATE 12-19-19 Conditions of Approval (If any):							

Well Name: North Vacuum Abo Unit #209 Location: 1980' FSL & 1780' FEL Sec: 22 Township: **17S** Range: 34E API: 30-025-23777 County: Lea State: NM KB: 4,054 **CURRENT** GL: 4,042' Spud Date: 5/25/1971 Surface Csg 8-5/8" CSG FAILURE. FOUND 8-5/8" Size: CRIMP AND SPLIT IN 8-5/8" ~6' Wt & Thrd: 23# **BELOW GROUND LEVEL. 5-1/2"** Grade: K-55 & 8-5/8" BOTH BENT Set @: 1,675 Sx Cmt: 700 Circ: Yes TOC: sfc PERF @ 1,725' **CEMENTED UNDER RETAINER @** 1,700'. **DRILLED OUT RETAINER - CMT** STILL GREEN. SD. RBP @ 8,505' W/ 2 SX SAND ON TOP **Production Casing** 5-1/2" Size: Guiberson "AN" Permanent Packer @ 8540' w/ 2.812" Wt & Thrd: 17# & 15.5# **OD Anchor Type SA** Grade: N-80 & J-55, STC & LTC Set @: 8,800' Abo Perfs: (1 JSPF) Sx Cmt: 2,900

8588-91', 8654'-70', 868'6-88', 8691'-92', 8697'-98',

8708'-10', 8713'-15', 8556'-64', 8567'-70', 8586-88',

8591'-93', 8696'-8700', 8708'-10', 8713'-20'

Circ:

TOC:

string

no

2,340' by TS

PBTD:

TD:

8,764

8,800'

2,021' of 17# casing on bottom of