
Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103		
District I - (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised Ju	lly 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	OIL CONSERVATION DIVISION		WELL API NO. 30-025-42207		
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran			RAL 🔲	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lease No. NMCL065863		
87505 SUNDRY NO	TICES AND REPORTS ON WELLS	. · · ,	7. Lease Name or Unit Agreemen	nt Name	
(DO NOT USE THIS FORM FOR PROP	OSALS TO DRILL OR TO DEEPEN OR PLU ICATION FOR PERMIT" (FORM C-101) FO	JG BACK TO A	Zia AGI		
1. Type of Well: Oil Well	Gas Well Other: Acid Gas In	jection Well	8. Well Number	#D2 🗸	
2. Name of Operator	Midstream L.P.	ENER	9. OGRID Number 36785	-	
3. Address of Operator	Austream E.T.		10. Pool name or Wildcat		
370 17	7th Street, Suite 2500, Denver CO 802	02	AGI: Devonian Exploration		
4. Well Location	./ /				
	etter L: 1893 feet from the SC	/ —	feet from the WEST line		
no Section	Township 198 Range 11. Elevation (Show whether DR,		County Lea		
	3,548 (GR)	KKB, KI, GK, etc.)			
12. Check	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data		
NOTICE OF I	NTENTION TO:	SUB	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK		REMEDIAL WOR		SING 🗌	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI			
PULL OR ALTER CASING		CASING/CEMENT	JOB 🗌		
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM	-	OTHER: (Machan	ical Integrity Test	\boxtimes	
OTHER: (COMPLETION)	, –	OTHER: (Mechan	cal integrity rest)		
13. Describe proposed or com	pleted operations. (Clearly state all p				
of starting any proposed very proposed completion or re-	vork). SEE RULE 19.15.7.14 NMAC	C. For Multiple Cor	npletions: Attach wellbore diagran	n of	
proposed completion of re	completion.				
	roviding notice to NMOCD on Th			y	
Robinson, (NMOCD) was on si	te to witness and approve the test.	Below is a step-	by-step summary and results:		
	sure between casing and tubing wa				
	sure was opened to a diesel line (p			l.	
	as bled down to 0 psig and a press			65 maia	
	re was slowly increased by pumpi essure reached 565 psig the valve				
	annular space pressure for 32 min		was closed. The Will began at	10.22 um.	
7. At 10:55 am the annulu	s pressure was 530 psig, a loss of	35 psig (6.2% dec			
	m the annulus to reduce the pressu				
	rom the truck, the annular pressur				
	nhead test was conducted by the Nessures. They remained unchange			liate and	
Please see the attached MIT pre	ssure chart (approved by NMOCI), calibration she	et, and Bradenhead test docume	ntation.	
<u> </u>	n above is true and complete to the be			· · · · · · · · · · · · · · · · · · ·	
Thereby certify that the information	i above is true and complete to the or	st of my knowledge	and belief.		
SIGNATURE DALT	Livish TITLE Consult		ID DATE 0.15	10	
SIGNATURE	TILE Consult	ant to DCP Midstre	am L.P. DATE <u>2-15-</u>	19	
Type or print name Dale T.	Littlejohn E-mail	address <u>: dale@ge</u>	plex.com PHONE: 505-842	<u>2-8000</u>	
For State Use Only					
APPROVED BY: Jary Kol	TITLE Cons	leave Offer	DATE 12-19-1	19	
Conditions of Approval (if arry):	•	"			



<u>ikudeli</u> a 25 fe februaren jiloma, bibliosta. Januaren 256 bunkolleren 1886 bun bild

HOBBS OCD

State of New Mexico : Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

FEB 1 9 2019

BRADENHEAD TEST REPORT

RECEIVED

214 AGI D	DCP Operation					30-025-42207 V		
Surface Location	2 174 AG2	r A	рену Маве			1	veli No.	
Well Status		<u> </u>	¹ Surface Loca	ıtion	*			
Well Status		Range Range					County /	
DESERVED DATA							1007	
Post Characteristics Post V/N					PRODUCER . GA	s 2	14-19 V	
Tessure Tes			one we so we are a second of	ns vers				
esture As Characteristics Full Steady How Norges Divide Gass Cas of OH Water Cas of OH Water Color with Cas of OH Cas of OH Water Color with Cas of OH Color can be not on the partial of the the partia			-					
Poil 17 No. 17 N		(Albertage	<u> </u>	S.M.cre(2)	<u>Dir</u>	od Csns		
Position Steady How 17 N 17		25	NA	N/x	7	872	1642	
Steady How 17 No. 17 No							co:	
Surges Description Description Construct White Construct Con								
Private rational Constraints of the Constraint o		1	1					
Tests of Off Volume Vol	"		[.		manusus de la companya della companya della companya de la companya de la companya della company	
entitiks - Prease state for each string (A.R.C.D.E.) perturent information regarding bleed down or combinious build up it applies. OIL CONSERVATION DIVISION Period name Emistred into RBDMS Period Re-itest Final Address:	·	(1	- Y :	. ` .		1	
Conservation Division Figure 1.22 Conservation Division Figure 2.22 Conservation Division Conservation Division Conservation Reduce Conservation Recognition Conservation Reduce Conservation Conservation Reduce	N Stoc	+	7 3	- 	N	100		
Proved ranse Entared into RBDMS Re-Nest E-mail Address:		each amag (A.D.C.D.t.) per	cacat informatica regarding	oktal down er concu		·	Ellinovice de Marie d	
France Re-Nest Re-Nest	Signature				OIL CO	The state of the s		
E-mail Address:			AND THE RESERVE OF THE PARTY OF	The state of the s			ION DIVISION	
Phana Phana			And Antonion and the second se		- h	BDMS	ON DIVISION	
Date Phone 11 9	Project name				- h	SBDMS	ION DIVISION	
	Project name				- h	SEDNS	ION DIVISION	

DCP Zia AGI D #2 As-Built Well Schematic

Well Name:

Zia AGI D#2

API:

30-025-42207

STR:

County, St.:

Sec. 19(L), T19S-R32E Lea County, New Mexico Footage: 13

1893' FSL & 950' FWL

Well Type:


Devonian AGI Expl.

KB/GL:

3574'/3547'

Lat, Long:

32.643950, -103.777782



Schematic is properly scaled

TD Location: Sec. 19, T19S-R32E (1963' FSL & 1024' FWL)