MAR 6 2019

		WAN 0 2010
Submit One Copy To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resource	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISIO	N 30-025-31462
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		5. State 6.1. 65 6.1. 25435 1.(6)
87505 SUNDRY NOTICES A	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well Gas V	Well Dther	097
2. Name of Operator		9. OGRID Number
Chevron Midcontinent		241333
3. Address of Operator 6301 Deauville Blvd., Midland, TX 7970	16	10. Pool name or Wildcat LOVINGTON Upper SA
4. Well Location:		BOVINGTON OPPER SA
Unit Letter D: 95 feet from the NORTH line and 115 feet from the WEST line		
	Range 36-E NMPM County <u>LE</u> Elevation (Show whether DR, RKB, RT, C	
3,903° GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTEN		SUBSEQUENT REPORT OF:
	JG AND ABANDON REMEDIA ANGE PLANS COMMEN	L WORK ☐ ALTERING CASING ☐ ' CE DRILLING OPNS.☐ P AND A ☐
		CEMENT JOB
TOLL ON ALTEN GAGING		16th
OTHER:		on is ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
A steel marker at least 4 in diameter and at least 4 above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
☐ The location has been leveled as near	ly as possible to original ground contour s	and has been cleared of all junk trash flow lines and
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution in		oles and fines have been removed from lease and wen
in the second se		
When all work has been completed, return	this form to the appropriate District offic	e to schedule an inspection.
SIGNATURE Katherine Paper	nosonos TITLE Decommiss	sioning Project ManagerDATE3.6.19
•		
TYPE OR PRINT NAMEKatherine Papageorge E-MAIL: _Katherine.Papageorge@chevron.com PHONE:832-854-5291		
APPROVED BY: Xerry Further TITLE Compliance Office A DATE 3-11-19		
APPROVED BY. Kenn forth.	TITLE COMPANY	100 Mico. A DATE 3-11-19
	11122	or force.
	•	