Submit One Copy To Appropriate District Office	State of New Mex	ico	Form C-103	
District I	Energy, Minerals and Natura	l Resources	Revised November 3, 2011	
1625 N. French Dr., Hobbs, NM 88240 District II		WELL AP	I NO. 30-025-41691	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION I	5. Indicate	Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. France	STA	ATE X FEE	
District IV	Santa Fe, MM 875	6. State O	il & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	APR	05 0:4 2019 6. State O		
SUNDRY NOTICE	S AND REPORTS ON WELLS	7. Lease N	lame or Unit Agreement Name	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLICE OF A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) CALSUCH PROPOSALS.)		AGE TO A PAPA SUCH	YA BVP STATE	
1. Type of Well: Oil Well  Gas Well  Other		8. Well N	umber #2	
2. Name of Operator		9. OGRID	9. OGRID Number	
EOG RESOURCES, INC		7377		
3. Address of Operator PO BOX 2267 MIDLAN	D, TEXAS 79702		ame or Wildcat RIDGE; BONE SPRING, N	
4. Well Location				
Unit Letter M: 200 feet from the SOUTH_line and 880 feet from the WEST line				
Section 10 Township 21S Range 34E NMPM County LEA				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3720' GL				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO:				
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING REMEDIAL WORK ALTERING CASING REMEDIAL WORK REME				
<del></del> -		CASING/CEMENT JOB		
	_  .	<b>.</b>		
OTHER:				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)				
All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines.				
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
The second conference of the second conference				
SIGNATURE KAM MADE	TITLE: REG	GULATORY SPECIALIST	DATE 04/01/2019	
TYPE OR PRINT NAME: KAY MADDOX E-MAIL: <u>kay maddox@eogresources.com</u> PHONE: 432-686-3658				
For State Use Only	DDOA E-MAIL. Kay_maddox	Macogresources.com PMOI	1L4J&-000-30J0	
, 1	+	. / · · · · · · · · · · · · · · · · · ·	1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1	
APPROVED BY: Xerry Fire	hh TITLE Co	mpliance Office 1	C DATE 4-9-17	
Conditions of Approval (if any		u yv		