

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-33301
Property Name New Mexico L State		Well No 018

2. Surface Location

U/L - Lot A	Section 1	Township 18S	Range 34E	Feet from 810	N/S Line N	Feet From 650	E/W Line E	County Lea
----------------	--------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	DATE 4/14/19
------------------	----------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	0	0	NA	20	380
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone	
Witness		