State Of New Mexico **Energy, Minerals and Natural Resources Department**

Michelle Lujan Grisham Governor Sarah Cottrell Propst

Cabinet Secretary Todd E. Leahy, JD, PhD **Deputy Cabinet Secretary** Adrienne Sandoval

Division Director

"Response Required - Deadline Enclosed"

Field Inspection Program "Preserving the Integrity of Our Environment"

14-Jun-19

CHEVRON US A INC 6301 Deauville Blvd Midland, TX 79706

LETTER OF VIOLATION - Field Inspection

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-025-38637] CENTRAL VACUUM UNIT #455

OGRID: 4323

D-36-17S-34E 1310 FNL 660 FWL

Inspection Date

Type Inspection

Inspector

Corrective Action Due By

Inspection No.

6/14/2019

Routine Inspection

[GR] Gary Robinson

9/12/2019

iGR1916529782

Violations:

Rule

Violation

19.15.26 Injection

Detection of Deficient Mechanical Integrity

BHT FAILED, RULE: 19.15.26.11, PROD CASING AND TUBING EQUILIZED PRESSURE, WELL TO

BE SHUT IN.

19.15 Oil and Gas Comment:

Mechanical Integrity Failure Recorded

Auto Generated Violation - MIT Failure exits.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division * 1625 N. French Drive * Hobbs, NM 88240 Phone: 575-393-6161 * Fax: 575-393-0720 * www.emnrd.state.nm.us

EMNRD OIL CONSERVATION DIVISION 1625 N FRENCH DRIVE HOBBS NM 88240



CHEVRON USA INC 6301 DEAUVILLE BLVD MIDLAND, TX 79706

State of New Mexico

BB CCO		- CP -		na Naturai K n Division Ho			•			
20 ⁶		E	RADE	NHEAD TEST	RE	PORT				
1 1999	Chevron Midcontinent, LP 3							¹ APi Number 0-025-38637		
Will Property Name Central Vacuum Unit						Well No. 455				
EC				Surface Location)					
Lut Section 36	Township 175	Range 34 E		Feet from	N/S	Line /	Feet From 660	E/W Line	County Lea	
				Well Status	_					
TA'D Well YES				INJECTOR SWD		PRODUCER OIL GAS		5-6	5-2-19	
			<u>OB</u>	SERVED DAT	[A .					

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csag	(E) Lubing
Pressure	0	900		ర	1845
low Characteristics				_	
Puff	Y/N	Y/N	Y/N	Y/(N)	C02
Steady Flow	Y/89	Y/N	N	Y76	WTR
Surges	Y (B)	Y/N	Y/8	V/V	GAS
Down to nothing	N (S)	Y/N)	Y/N	WN	If applicable type
Gas or Oil	Y/09	Y/N	Y/N	Y/82	fluid injected for
Water	¥7(\$P)	Y/N	Y/N	Y/(1)	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Failed - Built up	to 900 16s	on In	d. cosing	-			
			•				
	1						
Signature: MAN M				OIL CONSERVATION DIVISION			
Printed name:				Entered into RBDMS			
Title:			** ***********************************	Re-test	W/		
E-mail Address:	· · · · · · · · · · · · · · · · · · ·				P		
Date: 5-2 - 19	Phone:						
	Witness:						