

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
JUN 17 2019
RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-20781
Property Name Vacuum Glorieta West Unit	Well No 83 H

Surface Location

1/4 - Lot 2	Section 35	Township 17S	Range 34E	Feet from 1980	N/S Line S	Feet From 1785	EAV Line E	County Lea
----------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------



Well Status

TA'D Well YES (NO)	SHUT-IN YES (NO)	INJECTOR INJ SWD	PRODUCER (OIL) GAS	DATE 4-10-19
-----------------------	---------------------	---------------------	-----------------------	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	30	350
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: E. Carmone	Entered into RBDMS
Title: FSA	Re-test 
E-mail Address: E.Carmone@Chevron.com	
Date: 4-10-19	Phone: 575-200-6265
Witness:	