Submit 1 Copy To Appropriate District Office	State of New M		Form C-103
<u>District 1</u> – (575) 393-6161			Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		30-025-25025	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra		STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 8	1/202	6. State Oil & Gas Lease No.
97505			
SUNDRY NO (DO NOT USE THIS FORM FOR PROF DIFFERENT RESERVOIR. USE "APPI	TICES AND REPORTS ON WELL OSALS TO DRILL OR TO DEEPEN OR PI LICATION FOR PERMIT" (FORM C-101) F Gas Well 🗌 Other 🖾 SWD		<ol> <li>Lease Name or Unit Agreement Name</li> <li>H T Mattern NCT C</li> </ol>
PROPOSALS.)	Gas Well 🔲 Other 🛛 SWD		CDWell Number: 5
1. Type of Well: Oil Well       2. Name of Operator	Gas Well Other SWD	JULDON	9. OGRID Number
Chevron USA, Inc.		JUL 0 2 2019	4323
3. Address of Operator		RECEIVED	10. Pool name or Wildcat
6301 Deauville Blvd., Midlar	id, TX 79706	"""EIVED	Blineberry, Drinkard, Wantz, Abo
4. Well Location			d
Unit Letter I: 1980 feet f	from the South line and 330 feet from	n the East line	
Section 18 Township 21	S Range 37E, NMPM, County Lea	1	
	11. Elevation (Show whether Di		)
	3,491' GL		
12. Check	Appropriate Box to Indicate N	Nature of Notice,	Report or Other Data
	NTENTION TO:		
		REMEDIAL WOR	
TEMPORARILY ABANDON			
PULL OR ALTER CASING		CASING/CEMEN	
DOWNHOLE COMMINGLE			tjob Li pnk
OTHER:	, 	OTHER:	П
	pleted operations. (Clearly state all	pertinent details, an	d give pertinent dates, including estimated date
			mpletions: Attach wellbore diagram of
proposed completion or re	ecompletion. 9 5/8" 40# @ 1,307': 7	ГОС @ surface; 7"	23# @ 6,800': TOC @ 2,274'
Chevro	on USA Inc completed abandonme	nt of this well as fo	llows:
			e to L/D rods. MIRU CTU. Release TAC.
			JF. Attempt to pressure test CSG – failed.
			to pressure test CSG – failed. Tag TOC @
			32 YLD 14.8 PPG, F/ 6127' T/ 3800'. R/D
CTU. 06/05/2019: MIRU single rig. 06/06/2019: Tag TOC @ 3363'. Kerry Fortner(NMOCD) approved additional SKS on tag. Pressure test CSG to 600 PSI for 15 minutes – good test. Spot 20 SKS Class C, 1.32 YLD 14.8 PPG, F/ 3363' T/ 3243' Perforate @			
2652'. Unable to establish injection rate. Notified Kerry Fortner(NMOCD) and approved next plug. Spot 65 SKS Class C, 1.32			
YLD 14.8 PPG, F/ 2702' T/ 2364'. 06/07/2019: Tag TOC @ 2364'. Pressure test CSG to 1000 PSI – good test. Perforate @			
1370'. Established injection rate of 2 BPM at 1000 PSI. 06/10/2019: Perforate @ 1370'. Established injection rate of 1 BPM at			
900 PSI. Spot 90 SKS Class C, 1.32 YLD 14.8 PPG, F/ 1420' T/ 897'. 06/11/2019: Tag TOC @ 1093'. Notified Kerry			
Fortner(NMOCD). Performed bubble test - passed. M/P 25 BBLs MLF. Spot 25 SKS Class C, 1.32 YLD 14.8 PPG, F/ 1093 T/			
			le test – failed. 06/12/2019: Kerry
			9: Repeat bubble test – good test and no sign
of gas migration. Spot 110 SKS (	Class C, 1.32 YLD 14.8 PPG, 300'	T/0'. Good cemen	it to surface. RDMO.
I hereby certify that the informa	tion above is true and complete to	the best of my know	wledge and belief.
	6/18/2019		
${\sf X}_{\sf NickGlas}$			
	1(1)		
Nick Glann			
Well P&A Enginee	r/Project Manager		
SIGNATURE Signed by: Nick Gi	ann E-mai	l address: nglann@c	hevron.com PHONE: <u>432-687-7786</u>
For State Lise Only			

<u>For State Use Only</u> APPROVED BY: <u>Yerry forta</u> TITLE <u>Constitute Official</u> DATE <u>7~10-19</u> Conditions of Approval (if any)