

**HOBBS OCD**  
**JUL 12 2019**  
**RECEIVED**

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

**BRADENHEAD TEST REPORT**

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-38114
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 518

**7. Surface Location**

UL - Lot M	Section 18	Township 18-S	Range 38-E	Feet from 275	N/S Line SOUTH	Feet From 1030	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	------------------	-------------------	-------------------	------------------	---------------

**Well Status**

Well Status	SHUT-IN	PRODUCING	DATE 6-27-19
-------------	---------	-----------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**OBSERVED DATA**

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0	NA	NA	35	898
<b>Flow Characteristics</b>					
Puff	Y / (N)	Y / N	Y / N	(Y) / N	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	(Y) / N	
Gas or Oil	Y / (N)	Y / N	Y / N	(Y) / N	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Prod casing - puff of gas bleed down to 0 in 10 seconds

K E 6-27-19 Kellee Elston

Signature:		OIL CONSERVATION DIVISION	
Printed name: MENDY JOHNSON		Entered into RBDMS	
Title: ADMINISTRATIVE ASSOCIATE		Re-test	
E-mail Address: mendy_johnson@oxy.com			
Date:	Phone: 806-592-6280		
Witness:			