

HOBBS OCD

AUG 2 6 2019

Submit One Copy To Appropriate District Office	State of New M Energy, Minerals and Natu	RECEIVED	Form C-103 Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	mergy, witherais and water		WELL API NO.
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-33587
District III	1220 South St. Fran	ncis Dr.	5. Indicate Type of Lease STATE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8'	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			or state on or cas season.
	ND REPORTS ON WELLS	3	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			WEST VACUUM UNIT
PROPOSALS.)	,	oksoen	8. Well Number 056
1. Type of Well: ⊠Oil Well ☐ Gas V 2. Name of Operator	Vell Other		9. OGRID Number
Chevron USA Inc.			4323
3. Address of Operator	_		10. Pool name or Wildcat
6301 Deauville Blvd., Midland, TX 79700	<u> </u>		VACUUM GRAYBURG SAN ANDRES
4. Well Location:			
Unit Letter O: 100 feet from the SOUTH line and 2,450 feet from the EAST line Section 34 Township 17-S Range 34-E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
4,03	0' GL		
12. Check Appropriate Box to India	ate Nature of Notice, R	eport or Other Da	ita Jam
NOTICE OF INTEN	TION TO	SUBS	SEQUENT REPORT OF:
	G AND ABANDON	REMEDIAL WORK	
	NGE PLANS	COMMENCE DRIL	
PULL OR ALTER CASING MUL	TIPLE COMPL	CASING/CEMENT	JOB
OTHER:		☐ Location is rea	ady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
A steel market at least 4 in diameter and at least 4 above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment			
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution inf NOTE: Valve can on location is part of liv			·
NOTE: valve can on location is part of ity	z system.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE Katherine PapageorgeTITLEDecommissioning Project ManagerDATE8.26.19_			
TYPE OR PRINT NAME Katherine Panageorge E-MAIL: Katherine Panageorge@chevron.com PHONE: 832-854-5291			
APPROVED BY: Rick Rickman TITLE A/O 1 DATE 8-28-19			
APPROVED BY	KARA TITLE	1/01	DATE 8-28-19
THE TENED OF THE T			