HOBBS OCD

OCT 1.1 2019

Submit One Copy To Appropriate District Office	State of New	Mexico	Form C-103
District I	Energy, Minerals and N	Vatural RECEV	Revised November 3, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		, –	30-025-31287
811 S. First St., Artesia, NM 88210			5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. 1		STATE FEE
District IV	Santa Fe, NN	4 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			LOVINGTON PADDOCK UNIT
PROPOSALS.)			8. Well Number
1. Type of Well: Oil Well Gas Well Other			9. OGRID Number
2. Name of Operator CHEVRON MIDCONTINENT L.P	1		9. OGRID Number
3. Address of Operator	•		10. Pool name or Wildcat
6301 Deauville Blvd., Midland, TX 79706			LOVINGTON; PADDOCK
4. Well Location:			
Unit Letter_O: 1260_feet from the SOUTH line and 2585_feet from the EAST_line			
Section 36 Township 16-S Range 36-E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
an Cl. 1 A	3,977' GL	D 4 Od T	N-A-
12. Check Appropriate Box to	Indicate Nature of Notice	e, Report or Other L	Jata
NOTICE OF IN	TENTION TO:	l SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	_
TEMPORARILY ABANDON	CHANGE PLANS		ILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB
OTHER:		☐ Location is r	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE Katherine Papageorge TITLE Decommissioning Project Manager DATE 10.10.19			
TYPE OR PRINT NAMEKatherin	ne Papageorge_E-MAIL: _Ka	therine.Papageorge@cl	nevron.com PHONE:832-854-5291
For State Use Only			
APPROVED BY:	TITLE TITLE	$_{\rm F}$ C $_{\rm O}$	DATE 10-21-1
VIIVOAPD DI. TANA	111L	- 	DAIL