| UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENTIS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS | | | | | FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 | |
|---|--|--|--|---------------------------------------|--|--|
| B | UREAU OF LAND MANAGE NOTICES AND REPORT | S ON WELL | ad Fie | eld O | Serial No. | |
| Do not use the abandoned we | is form for proposals to dri II. Use form 3160-3 (APD) f | Il or to releft or such prop | FD H | obbs | 6. If Indian, Allottee or | Tribe Name |
| SUBMIT IN | TRIPLICATE - Other instruc | tions on | B 2 | | 7. If Unit or CA/Agree | ment, Name and/or No. |
| SUBMIT IN TRIPLICATE - Other instructions on 1992 | | | | • | 8. Well Name and No. ROJO 7811 34-27 FEDERAL COM 18H | |
| 2. Name of Operator BTA OIL PRODUCERS LLC | | ELLCEIVED | | 9. API Well No. 30-025-44297-00-X1 | | |
| 3a. Address 3b. Phone N | | | 0. (msnude area code) 32-3753 Evt: 139 | | 10. Field and Pool or Exploratory Area RED HILLS-UP BONE SPRING SHALE | |
| MIDLAND, TX 79701 4. Location of Well (Footage, Sec., 7 | Ph: 432-682-3753 Ext: 139 | | | 11. County or Parish, State | | |
| Sec 34 T25S R33E NESW 25 | | | | LEA COUNTY, NM | | |
| 32.086643 N Lat, 103.562347 W Lon | | | | | | |
| 12. CHECK THE AI | PPROPRIATE BOX(ES) TO | INDICATE | NATURE O | F NOTICE, | REPORT, OR OTH | ER DATA |
| TYPE OF SUBMISSION | TYPE OF ACTION | | | | | |
| Notice of Intent | | Deepen | Deepen □ Production (Start/Resume) Hydraulic Fracturing □ Reclamation New Construction □ Recomplete Plug and Abandon □ Temporarily Abandon | | | Water Shut-Off |
| 🛛 Subsequent Report | Alter Casing Casing Repair | — · | | | | Well Integrity Other Drilling Operations |
| Final Abandonment Notice | Change Plans | _ | | | | |
| | Convert to Injection | 🗋 Plug Bao | Plug Back Water Di | | Disposal | |
| determined that the site is ready for fi 3/25/2019: SPUD WELL 3/27/2019: DRILLED 14 3/4" H CEMENT CIRCULATED TO S | HOLE. SET 10 3/4" CSG (40. | 5# J-55 STC) SING TO 150 | @ 1135' WI | TH 765 SAC D TEST. | KS CEMENT. | <u> </u> |
| 4/9/2019: DRILLED 9 7/8" HO | LE. SET 7 5/8" CSG (29.7# F | P-110 BTC) @ |) 11,670' with | | s of | - |
| cement. CEMENT CIRCULATED TO SURFACE AFTER PUMPING 2 STAGES. 5/4/2019: TEST 7 5/8" CASING TP 2,750 PSI FOR 30 MIN. GOOD TEST. | | | | | | / |
| 5/21/2019: DRILLED 6 3/4" HO P-110 TXP-BTC 20,026' - 11,5 | OLE AND SET 5 1/2" X 5" C | | | G C @ 20,02 | 26" [(5" 18# | |
| | ····· | | | | | |
| 14. I hereby certify that the foregoing is | true and correct. Electronic Submission #4857 For BTA OIL PR unitted to AFMSS for processio | 783 verified by ODUCERS LL ng by PRISCIL | the BLM Well C, sent to the LA PEREZ on | Information Hobbs 09/30/2019 (| System (19PP3316SE) | |
| Name (Printed/Typed) KATY REDDELL | | | | ATORY AN | | |
| Signature (Electronic Submission) | | Dat | Date 09/30/2019 | | | |
| | THIS SPACE FOR I | FEDERAL C | R STATE (| OFFICE US | SE | |
| Approved By | | | Title Accepted for Record | | | QCT 0 8 2019 |
| Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject le which would entitle the applicant to conduct operations thereon. | | | Office Jonathon Shepard Carlsbad Field Office | | | |
| itle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s | | | | willfully to ma | ke to any department or a | gency of the United |
| Instructions on page 2) ** BI M BEVI | SED ** BLM REVISED ** | | | | ** BI M DE\/ICED | ** 1/2 |
| | | DEM VEAIS | | NEVIGED | dlini revijel | pic |
| | | | | | | |
| | | | | - | | |

V.

Additional data for EC transaction #485783 that would not fit on the form

32. Additional remarks, continued

P-110ICY TXP-BTC to surface)] with 1585 sx. Cmt circ to surface.

5/21/2019: RIG RELEASED.

6/16/2019: Test intermdiate casing to 1000 psi for 10 min, good test. Test production casing to 11,000 psi for 30 min, good test.