

District I
 1625 N. French Dr., Hobbs, NM 88249
 Phone (575) 391-8161 Fax (575) 393-0720

HOBBS OGD

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

DEC 23 2019

RECEIVED

BRADENHEAD TEST REPORT

Chevron Midcontinent, LP		Operator Name	API Number
State AN		Property Name	Well No
			30-025-03104
			004

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
H	7	18S	35E	1650	N	990	E	Lea

Well Status



TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES <input type="radio"/> NO <input checked="" type="radio"/>	YES <input type="radio"/> NO <input checked="" type="radio"/>	INJ <input type="radio"/> SWD <input type="radio"/>	<input checked="" type="radio"/> OIL <input type="radio"/> GAS	4/14/19

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod C'sng	(E)Tubing
Pressure	0	NA	NA	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflow

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well is Down Bad Pump - Rig is currently pulling well

Signature: 	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test 
E-mail Address:	
Date:	Phone:
	Witness: