Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERCORATISH OF THE ONE OF THE INTERCORATISH OF THE INTERCORATION OF THE INTERCOR

SUBMIT IN TRIPLICATE - Other instructions on page Of 1. Type of Well Gas Well Other					6. If Indian, Allottee or Tribe Name		
SUBMIT IN	TRIPLICATE - Other instr	ructions on	page O	166	If Unit or CA/Agreen	ment, Name and/	or No.
1. Type of Well					8. Well Name and No.		
					LESLIE FED COM	21H	
Name of Operator MATADOR PRODUCTION C	NK com	6. If Indian, Allottee or Tribe Name If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. LESLIE FED COM 21H 9. API Well No. 30-025-44543-00-X1					
3a. Address 5400 LBJ FREEWAY SUITE DALLAS, TX 75240	3b. Phone No. (include area code) Ph: 575-627-2465			10. Field and Pool or Exploratory Area DOGIE DRAW-DELAWARE			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, State				
Sec 17 T25S R35E SWSW 29 32.123955 N Lat, 103.394310		LEA COUNTY, NM					
12. CHECK THE A	PPROPRIATE BOX(ES)	O INDICA	TE NATURE	OF NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	☐ Acidize	Deep	en	☐ Production (Start/Resume)		☐ Water Shu	ıt-Off
	☐ Alter Casing	☐ Hydi	aulic Fracturing	g 🔲 Reclam	ation	☐ Well Integ	grity
Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	lete	Other ■	
☐ Final Abandonment Notice	Change Plans	Plug	and Abandon	□ Tempor	arily Abandon	Production S	tart-up
	☐ Convert to Injection	Plug	g Back				
If the proposal is to deepen directions. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f BLM Bond No: NMB0001079 Surety Bond:RLB0015172	rk will be performed or provide to deperations. If the operation resu pandonment Notices must be filed	he Bond No. on alts in a multiple	file with BLM/B: completion or re	IA. Required sul completion in a r	sequent reports must be f new interval, a Form 3160	iled within 30 da -4 must be filed o	iys once
Production Sundry 5/18/2019 Held prefrac meetir chart 5 minutes per procedure 5/21/2019 Perform casing interacid. Final pressure 4,729 psi 6/5/2019 WSI while frac amd 6/9/2019 Begin frac Stage 1 fr 40/70 4,564,550, 40/70 CRC	egrity test to 5,956 psi for 3 @ 3.6 bpm. WL operations are perform om/14,044'-9,644' on 6/30.	0 minutes. D led on adjace /2019 to Stad	isplace 2,000 g ent wells at rep ge 18. Commo	gals of 15%			
14. I hereby certify that the foregoing is							
Con	Electronic Submission #49 For MATADOR PR mitted to AFMSS for proces	ODUCTION D	OMPANY, sen	t to the Hobbs			
Name(Printed/Typed) TAMMY R LINK			Title PRODUCTION ANALYST				
Signature (Electronic Submission)			Date 12/06/	2019			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	SE		
Approved By			_{Title} Accep			DEC O	6 201
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				athon Shep sbad Field Of			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Additional data for EC transaction #494746 that would not fit on the form

32. Additional remarks, continued

7/19/2019 RDMO flowback equipment. Run in a jt of tubing w/TIN valves. Pressure tested BOP stack per procedure to 4,500 psi;p good test. 7/20/2019 Mill kill plugs. Drillout operations are complete. Racked & tallied 2 7/8" tubing, run joint of tubing with TIW valves. Pressure tested BOP stack per procedure to 4,500 psi; Good Test. 7/21/2019 Milled kill plug 1-17. 7/22/2019 Continued circulating sweep train. Ru Kelly hose and circulated 225 bbls of brine around to kill well. All tools recovered. Began to RD all equipment. 7/23/2019 Surface equipment has been released, continue to clean location. 7/28/2019 MU 2 9/16 5K production tree w/7 1/16" 10K adapter flange. Shell test to 5,000 psi. All test good. Turn well over to production.