

HOBBS OCD

Submit One Copy To Appropriate District Office

District I  
1625 N. French Dr., Hobbs, NM 88240District II  
811 S. First St., Artesia, NM 88210District III  
1000 Rio Brazos Rd., Aztec, NM 87410District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.  
Santa Fe, NM 87505

JAN 07 2020

Form C-103

Revised November 3, 2011

WELL API NO. 30-025-38145

5. Indicate Type of Lease  
STATE ☒ FEE ☐6. State Oil & Gas Lease No.  
V-25227. Lease Name or Unit Agreement Name  
FOX A STATE

8. Well Number 8

9. OGRID Number  
3711510. Pool name or Wildcat  
ALLISON SAN ANDRES

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator  
ROCKCLIFF OPERATING NEW MEXICO LLC3. Address of Operator  
1301 MCKINNEY; STE 1300; HOUSTON TX 77010

## 4. Well Location

Unit Letter K : 1650 feet from the SOUTH line and 2100 feet from the WEST line

Section 2 Township 9S Range 36E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
4049' GL

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐OTHER: ☐☒ Location is ready for OCD inspection after P&A

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- ☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- ☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**


- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- ☒ All other environmental concerns have been addressed as per OCD rules.
- ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
- ☒ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE  TITLE SR REGULATORY ANALYST DATE 01/07/2020

TYPE OR PRINT NAME JAMIE A ROBINSON E-MAIL: JROBINSON@ROCKCLIFFENERGY.COM PHONE: 713-351-0534

For State Use Only

APPROVED BY:  TITLE C O A DATE 1-13-20