Submit One Copy To Appropriate District	State of New Mexico	Form C-103
Office District I Energ	y, Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	•	WELL API NO. 30-041-20865
811 S. First St., Artesia, NM 88210 OIL	CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE ☑ FEE □
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	·	V-2096
87505 SUNDRY NOTICES AND	REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRI	LL OR TO DEEPEN OR PLUG BACK TO A	Fox C State
DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS.)	PERMIT" (FORM C-101) FOR SUCH	8. Well Number
1. Type of Well: Soil Well Gas Well	Other	4
2. Name of Operator	HOBBS OCD	9. OGRID Number
EOG Resources, Inc.	-2P2 OCD	7377
3. Address of Operator	JAN 2 8 2020	10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210	2 8 2020	Allison; Upper Penn
4. Well Location		
Unit Letter A: 660 feet from the North 510 feet from the East line		
Section 36 To	~~~	NMPM Roosevelt County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4060' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
Je 1		
NOTICE OF INTENTION		SEQUENT REPORT OF:
	D ABANDON REMEDIAL WOR	_
TEMPORARILY ABANDON CHANGE	·— I	
PULL OR ALTER CASING MULTIPL	E COMPL CASING/CEMEN	I JOB
OTHER:	☐ ⊠ Location is re	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The leastion has been leveled as mosely as mosely to evicinal arroyal contains and has been cleared of all jump treats flow lines and		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location.		
	n removed. Portable bases have been remo	ved. (Poured onsite concrete bases do not have
to be removed.)		
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
repetities and flow lines have been abandoned in accordance with 19.13.33.10 NMAC. All fluids have been removed from hon-retrieved flow lines and pipelines. No, active pipeline(s) within EOG Resources gas system.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastru		
When all work has been completed, return his form to the appropriate District office to schedule an inspection.		
SIGNATURE	TITLE: Environmental Sup	pervisor DATE 1/28/2020
SIGNATURE	TITLE. Elivacimiental Su	DATE 1/26/2020
TYPE OR PRINT NAME: Robert Asher	E-MAIL: Robert Asher@e	ogresources.com PHONE: 575-748-4217
For State Use Only		
	<i>C</i> ^	1 1000
APPROVED BY: Yelly Jut	TITLE CO	A DATE 1-29-20
Conditions of Approval (if any).		•