



FLARE INSPECTION

Mewbourn

LEASE OR FACILITY NAME: Cobra N:W 11 B3NE ST. Com

WELL # 1 H API # 30- 025 - 42597

U.L. 11 SEC 11 T 22S R 34E

FOOTAGE 260 N/S 1800 E/W (W)

IS A FLARE STACK PRESENT? (YES) NO

IS FLARE ACTIVE? YES (NO)

IS GAS TO FLARE METERED? (YES) NO

AREA AROUND FLARE CLEARED? (YES) NO

COMMENTS: Prod gas going to Sales

IS VRU PRESENT? (YES) NO

IS VRU ACTIVE? (YES) NO

COMMENTS: _____

INSPECTOR *Jay Robinson* DATE 3-20-20