



## FLARE INSPECTION

Newbourne

LEASE OR FACILITY NAME: Cobra Loca 11 B308 ST.

WELL # 1 # API # 30- 025 - 44002

U.L. 0 SEC 11 T 255 R 34E

FOOTAGE 200 N/E 2150 (E) W

IS A FLARE STACK PRESENT? ☒ YES ☐ NO

IS FLARE ACTIVE? ☐ YES ☒ NO

IS GAS TO FLARE METERED? ☒ YES ☐ NO

AREA AROUND FLARE CLEARED? ☒ YES ☐ NO

COMMENTS: Prod gas going to sales

IS VRU PRESENT? ☒ YES ☐ NO

IS VRU ACTIVE? ☒ YES ☐ NO

COMMENTS: \_\_\_\_\_

INSPECTOR Gary Rolinson DATE 3-20-20