



FLARE INSPECTION

Centennial Resources

LEASE OR FACILITY NAME: Tour Bus 23 ST.

WELL # 505 H API # 30- 025 - 44614

U.L. A SEC 23 T 22S R 34E

FOOTAGE 300 ~~NVS~~ 655 (E) W

IS A FLARE STACK PRESENT? (YES) NO

IS FLARE ACTIVE? (YES) NO

IS GAS TO FLARE METERED? (YES) NO

AREA AROUND FLARE CLEARED? (YES) NO

COMMENTS: _____

IS VRU PRESENT? (YES) NO

IS VRU ACTIVE? (YES) NO

COMMENTS: _____

INSPECTOR Gary Holmson DATE 3-20-20