

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.5. Lease Serial No.
NMNM1151

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 27. If Unit or CA/Agreement, Name and/or No.
73885U494B

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other8. Well Name and No.
EMSU-B 863

2. Name of Operator

XTO ENERGY INCORPORATED

Contact: CASSIE EVANS

E-Mail: cassie_evans@xtoenergy.com

9. API Well No.

30-025-04206-00-S1

3a. Address

6401 HOLIDAY HILL ROAD BLDG 5
MIDLAND, TX 79707

3b. Phone No. (include area code)

Ph: 432-218-3671

10. Field and Pool or Exploratory Area

EUNICE MONUMENT-GRAYBURG-

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 10 T20S R36E SESE

11. County or Parish, State

LEA COUNTY, NM

OCD - HOBBS
03/27/2020
RECEIVED**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

XTO Energy, Inc. respectfully requests a 1-Year TA extension pending a good MIT. This well is being evaluated for recompleat due to economics.

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #505277 verified by the BLM Well Information System
For XTO ENERGY INCORPORATED, sent to the Hobbs
Committed to AFMSS for processing by PRISCILLA PEREZ on 03/03/2020 (20PP1501SE)

Name (Printed/Typed) CASSIE EVANS

Title REGULATORY ANALYST

Signature (Electronic Submission)

Date 03/03/2020

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By JONATHON SHEPARD

Title PETROELUM ENGINEER

Date 03/20/202

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Hobbs

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED *****XZ NM OCP 4-3-20***Accepted for Record Only**

Revisions to Operator-Submitted EC Data for Sundry Notice #505277

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	TA NOI	TA NOI
Lease:	NMLC031740B	NMNM1151
Agreement:		73885U494B (NMNM70948B)
Operator:	XTO ENERGY INC 6401 HOLIDAY HILL RD #5 MIDLAND, TX 79707 Ph: 432-218-3671	XTO ENERGY INCORPORATED 6401 HOLIDAY HILL ROAD BLDG 5 MIDLAND, TX 79707 Ph: 432.683 2277
Admin Contact:	CASSIE EVANS REGULATORY ANALYST E-Mail: cassie_evans@xtoenergy.com Ph: 432-218-3671	CASSIE EVANS REGULATORY ANALYST E-Mail: cassie_evans@xtoenergy.com Ph: 432-218-3671
Tech Contact:	CASSIE EVANS REGULATORY ANALYST E-Mail: cassie_evans@xtoenergy.com Ph: 432-218-3671	CASSIE EVANS REGULATORY ANALYST E-Mail: cassie_evans@xtoenergy.com Ph: 432-218-3671
Location:		
State:	NM	NM
County:	LEA	LEA
Field/Pool:	EUNICE MONUMENT, GB-SA	EUNICE MONUMENT-GRAYBURG-SA
Well/Facility:	EUNICE MONUMENT SOUTH UNIT B 863 Sec 10 T20S R36E Mer NMP 990FSL 330FEL	EMSU-B 863 Sec 10 T20S R36E SESE

BUREAU OF LAND MANAGEMENT

**Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

Conditions of Approval for Temporary Abandonment of Wells

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.