## HOBBS OCD

, , , ;

.

.....

÷.

;

ADD 1 6 2020

		APR	1 6 2020	
Submit One Copy To Appropriate District	State of New Me	exico		Form C-103
Office District I	Energy, Minerals and Natu	Iral ResouREC	EIVED Revis	sed November 3. 2011
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u>			WELL API NO.	30-025-08665
811 S. First St., Artesia, NM 88210 District III	M 88210 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lea	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	ztec, NM 87410 Santa Fe, NM 87505		6. State Oil & Gas Leas	FEE
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Cone Jalmat Yates Pool	
1. Type of Well: Oil Well Gas Well Other			8. Well Number	703
2. Name of Operator Breitburn Operating LP			9. OGRID Number	370080 1
3. Address of Operator			10. Pool name or Wildo	
1111 Bagby Street, Suite 1600 Houston, TX 77002			Jalmat; Tan-Yates-7 Rivers	
4. Well Location	feet from the North line and 10	650 fact from the F	ast line	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3562'				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK DUID AND ABANDON DUID REMEDIAL WORK DIALTERING CASING D				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				
: =		CASING/CEMEN		
QTHER:		🗐 Location is r	and u for OCD inspection	offer D&A
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diame	ter and at least 4' above ground	level has been set in	n concrete. It shows the	
OPERATOR NAME, LEAS	E NAME, WELL NUMBER, A	API NUMBER, OI	JARTER/OUARTER LO	DCATION OR
	TOWNSHIP, AND RANGE.		ON HAS BEEN WELDE	<u>D OR</u>
PERMANENILY STAMPE	D ON THE MARKER'S SUR	FACE.		
The location has been leveled as n	early as possible to original grou	nd contour and has	been cleared of all junk, to	rash, flow lines and
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)				
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines.				
☐ If this is a one-well lease or last re		cal service poles an	d lines have been removed	from lease and well
location, except for utility's distribution	1 infrastructure.			· · ·
When all work has been completed, ret	urn this form to the appropriate I	District office to sch	edule an inspection.	
1.110			•	1
SIGNATURE MAN	TITLE	HSE Sperie	DATE	3-9-2020
TYPE OR PRINT NAME THOMAS	Haigo: E-MAIL:	thomas.haigood@n	navresources.com PHONI	E: 432-701-7802
For State Use Only				
APPROVED BY: KOM	For TITLE	-0		<u>те 4-17-</u> 20
F				