APR 1 6 2020

Submit One Copy To Appropriate District Office	State of New Mexico		ECEIVED	Form C-103
District I	Energy, Minerals and Natu	ıral Resources 🐃		Revised November 5, 2011
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API N 30-025-2291	1
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Ty	• •
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE	
District IV	Santa Fe, NM 87505			Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	ınta Fe, NM			3 345 2 345 7 101
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name HUGH COI	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well Gas Well Other			12	
2. Name of Operator			9. OGRID Number	
Chevron USA Inc. 3. Address of Operator			4323 10. Pool name or Wildcat	
6301 Deauville Blvd., Midland, TX 79705			Penrose Skelly, Grayburg	
4. Well Location:				,,,
Unit LetterC_ :330	feet from the NORTH line an	d <u>1650</u> feet f	rom the <u>WES</u>	<u>Γ</u> line
Section 14 Township 22-S Range 37-E NMPM County LEA				
11. Elevation (Show whether DR, RKB, RT, GR, etc.				
	3355' GL			
12. Check Appropriate Box to 1	indicate Nature of Notice, R	eport or Other I)ata	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		
	CHANGE PLANS	COMMENCE DR	ILLING OPNS.] PANDA 🗆
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB]
OTHER:				
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.) All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines.				
☑ If this is a one-well lease or last re		cal service poles an	id lines have bee	n removed from lease and well
location, except for utility's distribution	n infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE <u>Katherine Pa</u>	pageorgeTITLE	_Decommissioning	Project Manage	rDATE4.9.2020
TYPE OR PRINT NAMEKatherine Papageorge_E-MAIL: _Katherine.Papageorge@chevron.com PHONE:832-854-5291				
APPROVED BY: XMy At TITLE () A DATE 9-17-2				
AFPROVED BI: 100 VU	y / - IIILE ([(]	DATE