HOBBS OCD

Form 3160-4 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

MAR 1 2 2020

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

WELL COMPLETION OR RECOMPLETION REPORT RECEIVED

	MELLO	CHOL	ETION C	D DECO	SADI ETIZ	AL DE	DODT	RF(ᇩᇇ	ヒレ	5 1	ease Serial I	No.	
	WELL	OMPL	EHONC	R RECO	WIPLETI	JN KE	PORI	APRE			J. L.	IMNM2750)6	
la. Type of		Oil Well		_		Other				_	6. If	Indian, Alle	ottee or	Tribe Name
b. Type of	f Completion	Othe	ew Well r	□ Work O	ver 🔲 D	eepen 	Plug	з Васк	□ Diff. I	Resvr.	7. U	nit or CA A	greem 33	ent Name and No.
Name of Operator Contact: LAURA BECERRA CHEVRON USA E-Mail: LBECERRA@CHEVRON.COM												ase Name a D EA 29 3		ell No. COM P11 13H
3. Address 6301 DEAUVILLE BLVD. MIDLAND, TX 79706 British EdecENTA@CHEVRON.COM 3a. Phone No. (include area code) Ph: 432-687-7665											9. A	PI Well No.		30-025-44333
4. Location of Well (Report location clearly and in accordance with Federal requirements)*										10. Field and Pool, or Exploratory NEEDMORE TANK; UP WOLFCAM				
Sec 29 T26S R33E Mer NMP At surface NWNW 195FNL 828FEL 32.021226 N Lat, 103.600135 W Lon Sec 29 T26S R33E Mer NMP											11. Sec., T., R., M., or Block and Survey			
At top prod interval reported below NWNW 365FNL 397FWL 32.020758 N Lat, 103.601526 W Lon Sec 32 T26S R33E Mer NMP At total depth SWNW 47FSL 327FWL 32.000371 N Lat, 103.601714 W Lon											r Area Sec		26S R33E Mer NMF	
	depth SW	NW 47FS	SL 327FWL	32.000371					 		L	EA ´		NM
14. Date Spudded 05/26/2018 15. Date T.D. Reached 05/18/2019 16. Date Completed □ D & A ☑ Ready to Prod. 17. Elevations (DF, KB, RT, GL)* 3215 GL 17. Elevations (DF, KB, RT, GL)* 18/2019 17. Elevations (DF, KB, RT, GL)* 18/2019										3, RT, GL)*				
18. Total Depth: MD 19790 19. Plug Back T.D.: MD 19680 20. Depth Bridge Plug Set: MD TVD 12318 TVD														
21. Type Electric & Other Mechanical Logs Run (Submit copy of each) MUD LOG, MWD GAMMA 22. Was well cored? No Yes (Submit analysis) Was DST run? No Yes (Submit analysis) Directional Survey? No Yes (Submit analysis)														
23. Casing ar	nd Liner Reco	ord <i>(Repo</i>	rt all strings	set in well)										
Hole Size	Size/G	rade	Wt. (#/ft.)	Top (MD)	Bottom (MD)		Cementer epth		f Sks. & f Cement	Slurry (BB		Cement 7	Гор*	Amount Pulled
17.500	13.3	375 J-55	54.5	33	837	7			86	В			33	90
12.250 9.625 HCL-80		43.5		11593		4833	4833 3		0		4833		515	
8.500	5.50	0 P-110	20.0	33	19780	4—		-	281	2			5531	100
				-		 								
	. .				Ì	 		 		†	-			
24. Tubing	Record			·					-					
Size Depth Set (MD) Packer Depth (MD) Size Depth Set (MD) Packer Depth (MD)									Size	Depth Set (MD) Packer Depth (MD)				
25. Producii	na Intervale				126	. Perfora	tion Page	ved.		<u> </u>	Ц_			
	ormation		Тор	B,	ottom				Ι	Size	Τ,	No. Holes	1	Perf. Status
	ER WOLFO	AMP		2360	19623			forated Interval 12360 TO 196				130 OPE		
B)	21, 1102, 0				10020		'	2000 10	10020	<u> </u>			<u> </u>	
C)								,						
D)				<u>_</u>										
	acture, Treat		nent Squeez	e, Etc.				_						
	Depth Interva		200 070 444	DDI C TILII		DDODDA		mount and	Type of I	Material				
	1236	0 10 196	523 870,114	BBLS FLUI	7 & 2U. 1 MINI#	PROPPA	AN I							
28. Product	ion - Interval	A												
Date First Produced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gr Corr.		Gas Gravi	rv .	Product	ion Method		
01/28/2020	02/10/2020	24	\Box	1650.0	3168.0	4772.0				•		FLOV	VS FRO	OM WELL
		24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas:Oil Ratio		Well	Well Status					
31/128	Sī	3877.0					192		POW					
28a. Production - Interval B														
Date First Produced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Go		Gas Gravi	ty	Product	ion Method	_	
Choke Size	Tbg. Press. Flwg.	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas:O Ratio	il	Well	Status				
	SI													

⁽See Instructions and spaces for additional data on reverse side)
ELECTRONIC SUBMISSION #506530 VERIFIED BY THE BLM WELL INFORMATION SYSTEM
** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

		1.5													
	luction - Interv		Trees	Iou	Ic.	Tw	Tono :		Ic.:		Parallel Market				
Date First Produced	Test Date	Hours Tested	Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API		Gas Gravity		Production Method				
Choke Size	Tbg. Press. Flwg. Sl	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas:Oil Ratio		Well Sta	itus					
28c. Prod	uction - Interva	al D													
Date First Produced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API		Gas Gravity		Production Method				
Choke Size	Tbg. Press. Flwg. SI	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas:Oil Ratio	- "	Well Sta	'ell Status					
29. Dispo	sition of Gas(S	old, used j GAS	for fuel, vent	ed, etc.)	•	•									
Show tests,	nary of Porous all important a including deptl ecoveries.	ones of po	orosity and co	ontents there						31. For	mation (Log) Markers				
	Formation		Тор	Bottom	Bottom Description:			ns, Contents, etc.			Name	Top Meas. Depth			
	ional remarks (include pl	ugging proce	edure):						LAI BE CH BR BO AV	STILE MAR LL CANYON ERRY CANYON USHY CANYON NE SPRING LIME ALON ST BONE SPRING	3019 4840 4866 5885 7490 9028 9068 9930			
2ND 3RD WOL	MATION MD BONE SPRIN BONE SPRIN FCAMP A FCAMP A - T	IG 1 12,187	0,580 1,036 7 459												
	enclosed attac														
 Electrical/Mechanical Logs (1 full set req'd.) Geologic Report Sundry Notice for plugging and cement verification Core Analysis 										3. DST Report 4. Directional Survey 7 Other:					
34. I here	by certify that	the forego	-		ission #500	6530 Verifie	orrect as dete d by the BL SA, sent to t	M Well I	nforma		records (see attached instruct stem.	ions):			
Name	(please print)	LAURA E	BECERRA				T ₁	itle <u>REGU</u>	JLATO	RY SP	ECIALIST				
Signa	Signature (Electronic Submission)								Date <u>03/10/2020</u>						
Title 18 Un	J.S.C. Section	1001 and 1	Fitle 43 U.S.	C. Section 1	212, make	it a crime fo	or any person	knowingl	y and w	villfully	to make to any department or	agency			

Additional data for transaction #506530 that would not fit on the form

32. Additional remarks, continued

No tubing string, flowing from well. Tubing exception submitted.

***Corrected surface casing setting depth: 837', KB added.