HOBBS OCD

District 2 . 1625 N. Franch Dr., Hubbs, MM 88200 Flume: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico

MAY 0 1 2020

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

Oil Conservation Division Hobbs District Office				RE	CEIVED	
BRADENHEAD TEST REPORT API Number						
Marick Resources 30-					8647	
Cone Talmat Vates Pool Unit				10	VEIL NO.	
¹ Surface Location						
UT_Lot Section Township Range Foot from N/S Lips Foot From Post						
Well Status						
YES NO YES SHUT-IN NO INJ INJECTOR SWID OIL GAS DATE						
3/_21	·		- OIL	GAS U-	3-2020	
OBSERVED DATA						
	(AlSorber	(B)Interm(I)				
Pressure	0		(C)laterm(2)	(D)Prod Cang	15 min	
Flow Characteristics	-	9	\mathcal{N}	0		
Pull	(S) N	YIB			900	
Stendy Flow	YIN	YI(N)	N / N	Y7(B)	- 002_	
Surges	YIN	V/6	Y/N	YIR	WIR	
Down to nothing	(g) N	EDN	ALM	Y/(N)	GAS _	
Gas or Oil Water	Y (N)	¥1(B)	Y/N	(V) N	Typed Plate Injuries for	
Water	Y/N	YAR	YIN	N/W	- Waterface II	
				Y (N)	-	
Remarks - Please state for each string (A.B.C.D.E.) pertinent information regarding bleed down or continuous build up if applies.						
regarding bleed down or continuous build up if applies.						
· · · · · · · · · · · · · · · · · · ·						
Signature:						
1100				Off CONSERVA		
Printed name: VICOLO LL				OIL CONSERVATION DIVISION		
France Regulatory Compliand Tech				Entered into RBDMS		
a ment Montes.				Re-test		
Date: 412812000 Phone: 713-437-8050				 		
	Witness	14.0000				

INSTRUCTIONS ON BACK OF THIS FORM