HOBBS OCD

MAY 2 7 2020

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

State of New Mexico

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ³ API Number . PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating 30-025-30218 Property Name Well No. SKELLY PENROSE B UNIT 64 ⁷ Surface Location UL - Lot Section Township Range Feet from N/S Line Feet From E/W Line County F 5 23S 37E 2617 NORTH 1366 WEST LEA

Well Status

		ti en Status		
Ta' D Well	SHUT-IN	INJECTOR	PRODUCING	DATE
No	No		Oil	05/21/2020

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	<u>0#</u>			18	18
Flow Characteristics					
Puff	N	Y / N	Y / N	Y / N	
Steady Flow	N	Y / N	Y / N	Y - N	
Surges	Ň	Y / N	Y / N	Y - N	
Down to nothing	Y	Y / N	Y / N	Y / N	
Gas or Oil	N	Y / N	Ý/N	Y / N	\neg
Water	N	Y / N	Y / N	Y / N	<u> </u>

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR FRESH SALTY SULFUR BLACK

Remarks:		

Signature:		OIL CONSERVATION DIVISION	
Printed name: C. DALE KELTON		Entered into RBDMS	
Title: PRESIDENT		Re-test	
E-mail Address: providenceenergy@s	uddenlink.net		
Date: 05/26/2020	Phone: 432-661-1364		
	Witness:		