Hodas ocd

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

MAY 2 7 2020

RECEIVED

BRADENHEAD TEST REPORT Operator Name ³ API Number . PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating 30-025-30219 Property Name Well No. SKELLY PENROSE B UNIT 65 7 Surface Location UL - Lot Feet from N/S Line E/W Line Section Township Range Feet From County 4 23S 37E 1357 NORTH 15 WEST LEA D Well Status SHUT-IN INJECTOR PRODUCING DATE Ta' D Well 05/21/2020 No Oil No OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH **OBSERVED DATA**

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	<u>0#</u>			28	28
Flow Characteristics					
Puff	N	Y/N	Y / N	Y / N	
Steady Flow	Ň	Y / N	Y / N	Y - N	
Surges	N	Y / N	Y / N	Y - N	
Down to nothing	Y	Y / N	Y / N	Y / N	
Gas or Oil	N	Y / N	Y / N	Y / N	
Water	N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK

Remarks:

Signature	C.D.Kr-	OIL CONSERVATION DIVISION		
Printed name: C. DALE KEL	JTON	Entered into RBDMS		
Title: PRESIDENT		Re-test		
E-mail Address: providenceer	nergy@suddenlink.net			
Date: 05/26/2020	Phone: 432-661-1364			
	Witness:			