

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Chaparral Energy, LLC	Contact	J.R. Willingham
Address	701 Cedar Lake Blvd. OKC, OK 73114	Telephone No.	432-561-9462, 405-830-1217
Facility Name	West Dollarhide Queens Sand Unit #9	Facility Type	WIW

Surface Owner	BLM	Mineral Owner		Lease No.	30 025 12262
---------------	-----	---------------	--	-----------	--------------

LOCATION OF RELEASE


RP # 1514

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	30	24 S	38 E	2310'	North	2310'	East	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Saltwater	Volume of Release	25 BBL	Volume Recovered	0
Source of Release	1" valve at wellhead	Date and Hour of Occurrence	Weekend	Date and Hour of Discovery	7/24/07, 1500
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Buddy Hill and Chris Williams		
By Whom?	J.R. Willingham	Date and Hour	7/24/07		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			



If a Watercourse was Impacted, Describe Fully.*
None

Describe Cause of Problem and Remedial Action Taken.* Buddy Hill found old spill at #9 WIW. Looks like someone opened the valve and left open. Some time later the valve was closed but no one was informed about the discharge. No liquids are remaining. Notified NMOD by phone. All impacted soils were dug up and placed on visqueen on location.

Describe Area Affected and Cleanup Action Taken.* Fluid ran from well 125' X 2" down into an old rock pit. Covered an area approximately 30' X 40' and ran 40' X 2' into another area 10' X 10'. Plan on removing 12" to 24" deep soil and put on plastic. Replace same. On 7-27-07 met with Bill Grobe, land owner. He suggested we haul and dispose of contaminated soils. Once instructed by EH&S department, all impacted soils were taken to Sundance Services Disposal Facility for final disposal. Mike Griffin of Whole Earth Environmental took soil samples at spill site, but did not think there was any product remaining on site and therefore no samples would need to be sent in for analysis.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Kevin White</i>	OIL CONSERVATION DIVISION	
Printed Name:	Kevin White	<i>Johnson</i> ENVIRONMENTAL ENGINEER	
Title:	Environmental Engineer	Approval Date:	10-30-07
E-mail Address:	kevinw@chaparralenergy.com	Expiration Date:	_____
Date:	10/30/07	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	405-426-4358		

* Attach Additional Sheets If Necessary

RP# 1514