

DUPLICATE

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces, N.M.
Lease No. 060581
Unit J. T. Caudle Lease

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED
SEP 10 1951
U.S. GEOLOGICAL SURVEY
HOBBBS OFFICE

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 7, 1951, 19

Well No. 5 is located 660 ft. from N line and 660 ft. from E line of sec. 3

C/NE/4, NE/4, Sec. 3 T-12-S R-33-E N.M.P.
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Bagley-Siluro/Devonian Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

300' - Total Depth - Red Bld. Tested 10-3/4" casing & connections with 1000# for 1/2 hour - no pressure drop. After waiting on Cement for 18 hours, drilled Cement from 289' to 300'. Tested 10-3/4" casing & connections with 1000# for 1/2 hour - no pressure drop. Started drilling formation and 9-7/8" hole, at 10:30 AM, 9/5/51

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Amerada Petroleum Corporation

Address Drawer D, Monument, New Mexico

By Gen Topper
Title Assistant District Superintendent