

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Graridge Corporation, Box 752, Breckenridge, Texas
(Address)

LEASE Cap Unit WELL NO. 6-12 UNIT L S 6 T 13S R 32E
DATE WORK PERFORMED See Below POOL Caprock Queen

This is a Report of: (Check appropriate block) Results of Test of Casing Shut-off
 Beginning Drilling Operations Remedial Work
 Plugging Other See Below

Detailed account of work done, nature and quantity of materials used and results obtained.

- 5-30-58 Pulled rods and tubing and started cleaning out.
- 5-31-58 Finished cleaning out. Ran Gamma Ray & Caliper Logs.
- 6-1-58 Set 30' of 4 1/2" liner and cemented with 45 sacks cement. Top of liner @ 2991', bottom @ 3021.
- 6-4-58 Drilled cement, cleaned out, ran tubing and rods and put well back on production.
- 11-17-58 Pulled rods and tubing and converted to injection well. Water being injected into the open hole.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:
DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by <u>Mr. Paul Holloway</u>	<u>Graridge Corporation</u> (Company)	

OIL CONSERVATION COMMISSION
Name [Signature]
Title _____
Date 11 11 58

I hereby certify that the information given above is true and complete to the best of my knowledge.
Name (B. G. Harrison)
Position Manager of Secondary Recovery
Company Graridge Corporation