New Mexico

INCLINATION REPORT

1 FIELD NAME: Maljamar Grayburg San Andres	2 LEASE NAME: SEMGSAU #712 Unit P
3 OPERATOR: Cross Timbers Operating	
4 ADDRESS: 3000 Garfield, Midland, Tx. 79705	30-025-33695
5 LOCATION (Section, Block, and Survey): Sec.29, T-17-S, R-33-E, Lea, N.M.	330/S & 330/E

RECORD OF INCLINATION

*11. Measured Depth (feet)	12. Course Length (Hundreds of feet)	*13. Angle of Inclination (Degrees)	14. Displacement per Hundred Feet (Sine of Angle x 100)	15. Course Displacement (feet)	16. Accumulative Displacement (feet)
406	4.06	0.25	0.44	1.77	1.77
911	5.05	0.25	0.44	2.20	3.97
1408	4.97	0.25	0.00	0.00	3.97
2035	6.27	0.50	0.87	5.47	9.45
2380	3.45	1.00	1.75	6.02	15.47
2692	3.12	1.50	0.00	0.00	15.47
3110	4.18	1.25	2.18	9.12	24.59
3164	0.54	0.75	1.31	0.71	25.29
3539	3.75	0.50	0.87	3.27	28.57
3945	4.06	0.25	0.44	1.77	30.34
4460	5.15	0.75	1.31	6.74	37.08

Accumulative total displacement of well bore at total depth of 4,460' feet = 37.80' feet.

Inclination measurements were made in : ☐ Tubing ☐ Casing ☐ Open Hole ☒ Drill Pipe

Signature of Authorized Representative	Bobby L. Smith
L.V. Bohannon, Drilling Superintendent	Bobby L. Smith Drilling Engineer
Name of Person and Title (type or print)	Name of Person and Title (type or print)
Lakota Drilling Company	Cross Timbers Operating Company
Name of Company	Name of Company
Telephone 915-570-5560	Telephone (915) 682-8873
Area Code	Area Code

Certified By Jeanine Eaunders Date 12-16-97

JEANINE E SAUNDERS
Notary Public State of Texas
My Comm Exp Sept 18 1997