

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

COPY TO U. S. G.

SUBMIT IN TRIPlicate
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 063345

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
C. E. LaRue & B. N. Muncy, Jr.

3. ADDRESS OF OPERATOR
P. O. Box 196 Aretsia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980 FNL & 660 FWL; Section 4, T 18S, R 32E

7. UNIT AGREEMENT NAME
TR # 4A

8. FARM OR LEASE NAME
Pearsall Queen Sand Unit

9. WELL NO.
1 #

10. FIELD AND POOL, OR WILDCAT
Pearsall Queen

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA
Section 4, T 18S, R 32E

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, OR, etc.)
3864 GL

12. COUNTY OR PARISH
Lea
18. STATE
N. Mex.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)
PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) **plumbing for casing leak survey X**
REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Installed necessary plumbing for casing leak survey.

Two inch was plumbed to surface with a braiding head connection consistion of a 2000# valve. At or above the surface, a one inch swage was connected to a one inch 2000# valve.

Inspected and approved by Ms. W. Kelly; March 22, 1979.

RECEIVED

APR 24 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE **Overseer**

ACCEPTED FOR RECORD
DATE

(This space for Federal or State office use)

APR 24 1979

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

BOBBS TWM MEXICO
U. S. DEPT. OF STATE
MEXICO CITY

SEP 1 1954

RECEIVED

SEP 1 1954