

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Consolidated Oil & Gas, Inc.			Address 4150 E. Mexico Ave., Denver 22, Colo.			
Lease Midway State	Well No. 2-8	Unit Letter O	Section 8	Township 17S	Range 37E	
Date Work Performed 1-14-65	Pool Midway Abo			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

TD 8901' KB. Ran 2030.4' of 17# and 2619.6' of 15.5# J-55, 5-1/2" casing as liner. Hung liner at 4240' with B.O.T. hanger. Bottom of liner at 8900.3'. Equipped liner with float shoe and fill-up collar and cemented with 425 sacks Incor with 12% gel and 100 sacks Incor pozmix with 2% gel. Plug down at 1:45 a.m. Final pressure 1750 psig. WOC 48 hrs.

Witnessed by Tom Boyd	Position Area Sup't.	Company Consolidated Oil & Gas, Inc.
--------------------------	-------------------------	---


FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	TD	PBTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by 		Name Wayne Roper	
Title		Position Production Manager	
Date		Company Consolidated Oil & Gas, Inc.	